

Meridian 1

Option 11C

General Release Bulletin - 22.46

P0869285 Issue 4.0 March 1998

General Release Bulletin
Release 22.46

Meridian 1

Option 11C

General Release Bulletin - Release 22.46

Document Number: P0869285

Document status: Standard

Document Release: Issue 4.0

Date: March 1998

© 1998

All rights reserved

Printed in Canada

Information is subject to change without notice. Northern Telecom reserves the right to make changes in design or components as progress in engineering and manufacturing may warrant. This equipment has been tested and found to comply with the limits for a Class A digital device pursuant to Part 15 of the FCC rules.

Meridian 1 is a trademark of Northern Telecom.

Revision history

July 1997

Issue 1.0 Standard

August 1997

Issue 2.0 Standard

November 1997

Issue 3.0 Standard

Market Release of 22.46

March 1998

Issue 4.0 Standard

Addition of one manufacture installed patch to Chapter 1.

Contents

Introduction	xi
Chapter 1 — System Advisements	1
Systems Supported	1
System Hardware	1
Conversion	2
CCR - NACD Interworking (Release 22.46)	2
Companion Microcellular (Release 22.46)	4
Meridian 1 Network Management for Spectrum (Release 22.46)	7
New System Installations Using Basic Configuration	8
BUG5416	8
Meridian Administration Tool	8
System Security	9
Audit Routine	9
Basic Configuration	9
Use of BKO command in LD 43	9
Minimum Vintage for TDS/DTR pack - NTAK03DA	10
Backwards Compatible Daughterboard - NTDK26	10
Upgrading Option 11 and 11E to Option 11C using Pre-Installed Flash Daughterboard	10
Option 11C Internet Software Download Using PCMCIA	11
The Trunk Anti Tromboning, Network Call ID, and Network Call Page	11
AML EC11 disabled after upgrade	11

Multi-Channel Level Start/Control Mode	12
Meridian Mail Password Suppression	13
M2008HF (Handsfree) Sets	14
Filter TTY Changes	14
M-1 Digital set template conversion to X11 Release 22	14
ISDN Q.Sig	14
Software Patches	15
Chapter 2 — Documentation	21
Documentation Structure	21
Base Package	22
Optional Documents	25
Chapter 3 — Features Overview	27
Platform Evolution	28
Station Features	29
Networking Features	30
Call Center	36
System Enhancements	37
OA & M	41
Chapter 4 — Overlays	45
Administration Overlays	45
Maintenance and Diagnostic Overlays	47
Chapter 5 — Software Packaging	49
Software Options and Package Dependencies	49
Packages Introduced in Release 22	69
Packages not supported on Option 11C	70

Chapter 6 – Resolved Problems	71
References	91
Appendix 1— Option 11C Product Overview	97
Introduction	97
Overview	97
System Highlights	98
Software	100
Hardware	100
NTAK02BB Introduction	102
Product Description	102
System Core Card (NTDK20)	102
Flash Software Daughterboard (NTDK21)	105
Fiber Daughterboards (NTDK22 & NTDK24)	106
Fiber Receiver Packs (NTDK23 & NTDK25)	107
Backward Compatible Daughterboard (NTDK26)	108
Cabinets	108
Fiber Optic Cables	109
Fiber Specification	109
Ethernet Interface	110
PCMCIA Cards	111
Customer Database Upgrade Tool	112
Tools Impact	112
Meridian Administration Tool	112
Meridian Configurator	113
Meridian Mail	113
Customer Database Upgrade Tool	113
Software Delivery Impact	113
Upgrading an existing Option 11/11E to Option 11C	117
Upgrading Option 11C Software	120
Auxiliary Products Compatibility	122

Introduction

This document provides an overview of the features developed for the Meridian 1 Generic X11 Release 22 software product, including the changes introduced with 22.46. It describes the new features and enhancements offered in this release.

X11 Global release 22.46 is a multi-purpose release designed to deliver a single global software stream to all markets. X11 Global Release 22.46 is supported on the following Meridian 1 systems: Option 11C, Option 51C, Option 61C, Option 81, and Option 81C. This document only applies to Option 11C systems. For other system details, please refer to Meridian 1 General Release Bulletin (for other Meridian 1 systems).

One of the major hardware deliverables for X11 Global Release 22 is the introduction Meridian 1 Option 11C system. This document provides a product overview of Option 11C, new Software Delivery Mechanism, and upgrade procedures.

For more details on feature installation and operation, hardware upgrade procedures, refer to the Option 11C Nortel Publications (NTPs).

For details on the Meridian Mail Option, the Central Answering Position feature, the Autoconfiguration feature, Model Sets and Administration Sets, as well as installation and operation, please refer to the Northern Telecom Publications (NTP) provided with the Option 11.

Note: Not all features described in this document are offered in all countries. Please contact your local Northern Telecom sales representative for more information.

Note: For information on Real Time requirements, please contact your local Northern Telecom sales representative. For information on Memory calculations, please refer to publication 553-3011-100, and Technical Reference Guide.

IMPORTANT

Please read all included advisements, requirements, and enhancements prior to loading this software.

Chapter 1 — System Advisements

X11 Release 22.46 is a global software release. This document provides the advisements specific to Option 11C X11 22.46.

Systems Supported

Generic X11 Release 22 supports the following machine types:

— Meridian 1 Option 11C, 51C, 61C, 81, 81C

This document includes information specific to Option 11C system only, for all other Meridian 1 systems, please refer to Generic X11 Release 22 General Release Bulletin and Nortel Publications (NTPs).

System Hardware

With the introduction of Global X11 Release 22.08D, Meridian 1 introduced the newest member to its commercial processor based system portfolio - Option 11C. The Option 11C expanded the functionality of the already popular Option 11/11E and introduced several new enhancements which establishes the Option 11C as the industry's most powerful, flexible, and feature rich system in the 30-400 line size.

Please refer to Product Overview chapter for more details.

No new hardware is being introduced on Option 11C with the introduction of X11 Release 22.46.

Conversion

The Option 11/11E Systems running on pre Release 22 software require a hardware upgrade in order to upgrade to the Release 22 software. The Option 11C system offers a menu driven installation and upgrade method. Please refer to the Option 11C Installation Guide and/or the Upgrade Procedures Guide for additional information.

CAUTION

Please read the Option 11C NTPs thoroughly before performing any hardware/software conversions. All conversion procedures should be strictly followed step-by-step.

To avoid static discharge, wear a properly connected anti-static wrist strap when working on the Meridian 1 equipment.

CCR - NACD Interworking (Release 22.46)

CCR-NACD Interworking provides greater control for calls that need to be placed in multiple queues throughout a private ISDN enterprise network. With this enhancement a call can be logically placed into many queues throughout the network using the “Queue To” command, while the local Customer Controlled Routing (CCR) system maintains control over the call. Once a remote target agent is reserved by NACD, a call will be removed from the source Control Directory Number (CDN) queue and presented to the reserved target agent.

If the source node is running ACD-C reports, Call Accepted, Call Answered and Abandoned fields of CDN Report 2 will be pegged for a Queue to NACD call. TOF Out field of ACD DN (NACD Routing DN) Report 2 will be pegged when a Queue to NACD call has been answered by the remote target agent. If the source node is running ACD-D reports, a new QTN field will be added to existing Call Enter Queue (IECQ), CCR Call Cancel (ICCN), Network Call Overflowed (NOVF), Answered by Remote Agent (RCAA) and Network Call Released (NCRL) MAX messages to indicate the MAX message is sent for a queue to NACD call. High Speed Link (HSL) Protocol 11 or higher (i.e. MAX 8B) will reflect these changes in the reports.

If the remote target node is running ACD-C or ACD-D reports, the incoming Queue to NACD calls will be pegged like NACD calls. The source ACD DN for a Queue to NACD call would be a source CDN instead.

There is no restriction for the Queue to Command to a NACD Routing DN that the HSL Protocol be at least Release 11. The Queue to Command will still work with HSL Protocol 10 or lower. The only thing that will be affected by this are the MAX reports. If the HSL Protocol is 10 or lower, the MAX messages will not contain any new information and the length of the messages will remain the same.

A new package is required for CCR - NACD Interworking, Option 321. There are no changes required in CCR or OA&M.

Refer to Product Bulletin 97-041 for further information.

NOTE

Patches are required for systems running NACD-CCR Interworking. The patches are required on the source node only. Please contact the Nortel CTS organization and provide the following reference number to obtain the required patches: BV67504.

Companion Microcellular (Release 22.46)




Figure 1 Using a single standard cellular portable, the Microcellular product provides in-building and wide-area wireless communications.

Companion Microcellular provides users both in-building and wide area mobility using a single standard cellular portable. Within the Microcell coverage area (in-building), the Microcellular system delivers wireless communications and popular Meridian 1 features including CLID, Message Waiting Indication, transfer and conference to the cellular portable user. No cellular air-time charges apply to calls made from within the Microcellular system's coverage area. When outside the microcell's coverage area, users may make and receive calls throughout the macrocellular network with the same cellular portable.

The Microcellular product also provides personal mobility across multiple Meridian 1's within an enterprise network and works in Remote-IPE configurations. Microcellular is fully integrated with the Meridian 1 PBX, but may also be used as an adjunct behind most other PBXs.

Microcellular uses the North American 800 MHz licensed cellular band; the required cellular channels must be provided by a Cellular Operator. Based on TDMA technology, the system supports the latest digital standard, IS-136 (DCCH), as well as IS-54(B) protocols.

Microcellular is supported on Meridian 1 Options 11C, 51C, 61C, 81 and 81C running X11 Release 22. Each Meridian 1 equipped with Microcellular requires MOSR (Option 302) and MMO (Option 303). Each Meridian 1 using the Multi-Site Networking feature must also have MMSN (Option 314). MAT 5 is also required, along with the Mobility System Management application. (Additional information on system configuration and pre-requisites can be found in the Microcellular NTPs: 553-3611-100, 553-3611-105, 553-3611-200, 553-3611-300 and 553-3611-110).

Two IPE cards, the Embedded Intelligent Mobility Controller (EIMC) and the Microcellular Transcoder Card (MXC), are required. The EIMC is the wireless controller, while the MXC provides the voice transcoding function and base station interface via standard twisted pair wiring (TCM).

The Microcellular Base Stations contain the radios and may be placed at various locations within the building, up to 3,000' away from the Meridian 1. All radio channels may be simulcast onto all antennas within the same partition to cover high density areas economically. A distributed antenna system, composed of directional antennas connected to the base stations via coaxial cable, is used to provide coverage. A directional antenna can usually cover up to 200 linear feet.

Microcellular uses industry standard, dual-mode AMPS/TDMA portables. IS-136 portables offer extended battery life and talk-time.

All OA&M functions are fully integrated with the Meridian Administration Tool (MAT).

NOTE

In Canada and the United States, the Microcellular Feature is not available for Release 22 on the Option 11C General business package. For other regions, please refer to the regional price book.

Key Microcellular features include:

-Single handset: One cellular portable for both in-building and wide area communications minimizes handset investment.

-Twinning: The cellular portable and the wired set may be assigned the same Directory Number, allowing calls to be presented simultaneously to both devices. Call treatment preferences are preserved and users may answer calls on either device.

-Privacy: When the desk set is twinned with the portable, Privacy prevents a call answered on the portable from appearing on the desk set.

-Cellular Spectrum Re-Use: Use of licensed spectrum eliminates interference concerns.

-High capacity: Supports up to 1,500 users per system.

-Large Coverage: Microcellular can cover large sites or campus environments. It can also support high density applications.

-Ease of Expansion: Capacity can be increased by adding radios to the base stations and additional IPE circuit packs, if necessary.

-Security: TDMA digital technology makes it extremely difficult to eavesdrop.

-Data Capabilities: Microcellular offers 9,600 baud data transfer capabilities for applications such as fax and e-mail.

-Multi-Site Roaming: Microcellular allows roaming among Meridian 1 systems connected via a Primary Rate Interface (PRI) through use of the Mobility Multi-Site Networking feature package.

-Access to popular PBX Features: Meridian 1 integration offers cellular portable users Message Waiting Indication, CLID, call transfer, 3-party conference, etc. while operating within the Companion Microcellular coverage area.

For more information, refer to the Sales and Marketing Mulletin 1100-G and Product Bulletin 97-044.

Meridian 1 Network Management for Spectrum (Release 22.46)

The Open Alarm feature of X11 facilitates the management of Meridian 1 networks from an open network management platform. The Open Alarm feature is used to implement the M1 fault management function on SPECTRUM. SPECTRUM is an open network management platform developed and marketed by Cabletron Systems. The SPECTRUM provides the ability to monitor and maintain voice and data networks. Alarms from Meridian 1 network can be monitored on a single window along with the alarms from the other elements managed as a part of the enterprise network. In addition, fault management functions of MAT 5 are integrated with SPECTRUM to complete alarm management. Using these MAT5 functions, user can view the events for Meridian1, exercise maintenance functions on components of M1, and access overlay commands.

Package #315 is required for Meridian 1 Network Management for Spectrum.

SPECTRUM provides a set of applications assisting the technician and network operations managing an enterprise network effectively.

SpectroPHONE -- SpectroPHONE enables network managers to be notified and respond to alarms remotely via a touch-tone phone. Configuration allows many options including alarm severity and support territory.

Remedy Trouble-Ticketing -- Spectrum is integrated with the Remedy Trouble-Ticketing system to facilitate the creation and automation of problem tracking and resolution.

Spectrum Report Generator -- Spectrum offers many options for report generation using its own report generation tools as well as third-party applications. Reporting tools allow for the creation and customization of reports for statistical and inventory details. Statistical data can be exported as ASCII output to be used by external database products.

Spectrum Alarm Notification Manager -- Spectrum Alarm Notifications Manager is a policy-based alarm filtering tool that can be used in conjunction with other Spectrum applications. It reduces the number of alarms that network managers need to view in order to isolate a network fault.

For more information, refer to Sales and Marketing Bulletin 1105-G.

New System Installations Using Basic Configuration

The following note is specific to Release 22.16 and later on new system installations only:

In selecting Basic Configuration on a new system installation, you will see the following:

- Data conversion from 22.12
- SYS4691 BTDT 0 message output
- sysload will report problems found.

NOTE: the sysload DOES complete successfully. In order to prevent future data dump problems, as soon as the sysload is complete, please use the EDD CLR command in overlay 43. This command sequence is only required once and will completely clear the problem going forward.

BUG5416

BUG5416 is a new BUG message.

BUG5416: Conference timeslot will not setup/teardown properly.

Meridian Administration Tool

Meridian Administration Tools (MAT) Release 4.5 now supports X11 Release 22 as well as systems running X11 Release 14, 17, 19, 20 and 21. MAT Release 4.5 is designed for the Windows 3.1 operating system. MAT Release 4.5 provides the following Applications: Station Administration, Traffic Analysis, Call Accounting and Call Tracking.

Meridian Administration Tools (MAT) Release 5 is introduced with X11 Release 22 and requires the Windows 95 Operating System. MAT Release 5 provides the following applications: Station Administration, Traffic Analysis, Call Accounting, Call Tracking, Maintenance Windows, ESN Analysis and Routing Tool, and Alarm Management.

MAT Release 5 also supports connectivity to Meridian 1 via Ethernet for System Options 11C, 51C through 81C running X11 Release 22. If MAT 5 is connected to a System type of 51C through 81C via Ethernet the following minimum vintage cards and cables are required:

- NT5D20BA (Release 01) - IOP/CMDU Card
- NT6D63BA (Release 01) - IOP Card (1 for each IOP/CMDU or IOP card)
- NT7D90DA (Release 01) - Ethernet Cable

Note: If MAT is connected via Ethernet a revised Parallel Upgrade procedure must be followed to ensure that the primary IP address remains active following a software upgrade. Please refer to the MAT Release 5 Common Services User Guide Release 5.0 (part number A0858266) for further details.

System Security

Nortel strongly recommends changing the default system passwords for both Meridian 1 and Meridian Mail systems during initial installation. These passwords should be changed again when the system is placed in active service. These actions will help deter unauthorized system access which can result in toll fraud or system abuse.

For more information, please refer to the Sales and Marketing Bulletin #807G, or the System Security Management NTP (553-3001-302).

Audit Routine

As in the case of previous software releases, it is recommended that the Audit routine (Overlay 44) be specified as the background diagnostic to optimize the system capability to deal with call processing anomalies, especially in large line size and high traffic configurations.

Basic Configuration

On Release 22.08D, the “Basic Configuration” default data option provided only a configuration record and no other customer data.

During Option 11C installations on 22.08 some installers were choosing “Basic Configuration” data option expecting to have default data including superpose etc. Once the installation is completed using this option, the XPECs & superloops will be have to be defined manually. Also, when the data dump is done in this scenario, an invalid data record error is given.

With X11 Release 22.16, the “Basic Configuration” data option was expanded to include default data such as XPECs, Superloops, and other default data blocks. It doesn’t include Model sets, routes, TN’s etc. For complete default data including model sets etc., choose the Pre-Configured data option.

Use of BKO command in LD 43

The BKO command is used to backup the customer data to an external data card (blank PCMCIA card) located in the slot “B” on the CPU faceplate.

Warning: If the pre-programmed software PCMCIA card is used during BKO operation, then the card cannot be used to install software.

Minimum Vintage for TDS/DTR pack - NTAK03DA

The minimum vintage for TDS/DTR pack is NTAK03DA. For packs older than the NTAK03DA version, SDI functionality will not function properly. The NTAK03DA version was introduced to the market in Feb. 1993.

Please note that the new Small System Controller pack (NTDK20) provides built-in TDS/DTR and SDI capabilities.

Backwards Compatible Daughterboard - NTDK26

The backward compatible daughterboard allows the Option 11/11E two cabinet (copper) systems to be upgraded to Option 11C maintaining copper connectivity.

The NTDK26 has a hardware key that prevents installation when the ethernet jumper (J7) is installed.

The ethernet jumper plug (J7) on the NTDK20 (Small System Controller) pack **MUST** be removed before the NTDK26 daughterboard is installed.

Note: Ethernet is not supported in this configuration

Upgrading Option 11 and 11E to Option 11C using Pre-Installed Flash Daughterboard

If the installer pre-installs customer feature set and data on the pre-programmed software daughterboard prior to delivery of the Option 11C hardware to the end customer, the following steps must be performed after they sysload their Option 11C with the pre-installed feature set and default data.

1. Ld 143 and type “upgrade”
2. Select option 3 “Utilities” from the main menu.
3. Select option 1 “Restore Backed up Database” from the Utilities menu.
4. Select option 4 “Option 11/11E CCBR File “OR option 5 “Option 11/11E Software cartridge” (After selecting this option the user is prompted to insert the Database Upgrade Tool.)
5. Sysload.

Internet Software Download Using the PCMCIA Card

Details of the Option 11C Internet Software Download process are found in P0866881. An Internet Registration Kit is required - contact your Nortel representative for ordering information.

Before copying the software executable file from the internet onto your PCMCIA card, ensure the PCMCIA card you are using is blank by clicking on the PCMCIA drive, and displaying the contents of the device. If any files appear on the card delete them.

Important: Delete the executable file from the PCMCIA card after it has executed, so that only the Option 11C software file structure remains.

The Option 11C software will have the following directory and file structure:

- bootrom/
- dflt_db/
- p/
- u/
- dramos
- dramos.sym
- dramoscc.sym
- readme.txt

The Trunk Anti Tromboning, Network Call ID, and Network Call Page

These features are supported for Option 11C in ISL/VNS configuration. The minimum vintage required for the SDI/DCH pack which supports these features is NTAK02BB.

AML EC11 disabled after upgrade

If an EC-11 Mail connected to Option 11C through AML over the NTAK02 (SDI/DCH) pack, the AML link does not come back into service after a software upgrade of the Option 11C system.

WORKAROUND:

- 1) Disable the AML before the software upgrade, or
- 2) Re-seat the NTAK02 (SDI/DCH) pack after upgrade

Multi-Channel Level Start/Control Mode

A new RAN mode of operation is available. In RAN terminology, this mode is called Multi-Channel Level Start/Control mode (MLSS). With Multi-Channel Level Start/Control mode, customers can provision separate individual RAN channels (or messages) to each RAN trunk member. The maximum length of the message for the new MLSS RAN mode is 608 seconds. The RAN software package (Option 7) and Intercept Treatment software package (Option 11) must be equipped.

The technician must cross connect one RAN channel to each EXUT RAN trunk unit. The connection of multiple EXUT's to a single RAN channel is not supported by the MLSS mode.

Note: Enhanced Universal Trunk Cards (NT8D14BA vintage or greater) are required to support the new MLSS mode. EXUT vintages prior to the NT8D14BA can not support the MLSS mode.

Service Change

In the Route Data Block (LD 16), a new RAN prompt (MLSS) is introduced to support this scenario. To configure a RAN Route in Multi-Channel Level Start/Control mode, the following prompts and responses must be followed:

Route Data Block (LD 16)

Prompt Response

TKTP RAN

RTYP **MLSS**

Once RTYP = MLSS is selected and RDB provisioning is complete, trunk members are provisioned in LD 14 via existing service change prompts & responses.

Trunk Data Block (LD 14)

Prompt Response

TYPE RAN

XTRK EXUT

Meridian Mail Password Suppression

Meridian Mail Password Suppression provides a new AML message which prevents a Meridian Mail user's log on password from being echoed on a set's display. Meridian Mail Release 11 is required. No new software package is introduced by this feature but Meridian Mail requires the existing package Call ID (CALL ID) package # 247. In addition the following packages are also required: Digit Display (DDSP) package # 19, Command Status Link (CSL) package #77 and Basic ACD (BACD) package # 40.

Table 1: Package Sets Supporting Password Suppression (All regions except Europe)

	22.08D	22.16	22.46
US / Canada	Enterprise Business NAS/VNS	ALL Package Sets	ALL Package Sets
CALA	Networking Advanced Applications	ALL Package Sets	N/A
Asia Pacific	Advanced Applications	ALL but General Business	ALL but General Business
Japan	Networking Advanced Applications	Networking Advanced Applications	Networking Advanced Applications
Australia / New Zealand	N/A	ALL but General Business	ALL but General business

Note: For Canada and US sites on 22.08D who wish to have password suppression on General Business and Enhanced Business feature sets, please order NTSF8509 (A0679053). This is a no charge item. A new keycode data sheet will be sent which will turn on package 247.

M2008HF (Handsfree) Sets

This functionality provides the capability to configure/install M2008HF with handsfree. This means M2008HF sets can/should be equipped with the handsfree feature. To turn on the feature on the set, enable the class of service HFA (handsfree allowed) in Overlay 11. If MAT is equipped, a patch is required for MAT Release 4.02 and later to support this feature. Sites running MAT Release 3 and below cannot be patched to support this operation. Sites with MAT Release 3 and below must upgrade to MAT Release 4.02 and later and obtain a patch to support the M2008 handsfree operation. Please contact your Technical Assistance Center for insertion of the patch.

Filter TTY Changes

When doing an upgrade to Release 22, the filter TTY (USER = FIL in Overlay 17) operation has changed. The filter TTY will only print alarms that are marked as critical in the Event Default Table (EDT) in Overlay 117 after upgrading to Release 22. Alarms which are marked as critical in the Event Default Table (EDT) can be made to print on the FIL TTY by adding them to the Event Preference Table (EPT) in Overlay 117 and changing the severity to critical. Note that this functionality is different than on prior releases.

M-1 Digital set template conversion to X11 Release 22

It has been determined that under rare circumstances during a software conversion from X11 Release 21 to X11 Release 22.08D there is a possibility of exceeding the maximum amount of memory that has been allowed for a BCS template. Reference PRS number BV54368.

This problem was fixed on X11 Release 22.16 software.

ISDN Q.Sig

ISDN Q-Sig is the standards-based definition of the Integrated Services Digital Network (ISDN) “Q” Signaling (Q-Sig) reference point for private PBX-to-PBX interworking. This ISDN Layer 3 protocol has been defined by the European Computer Manufacturer's Association (ECMA) and adopted by the European Telecommunications Standards Institute (ETSI) for Europe and by the International Standards Organization (ISO) for global introduction.

Nortel has completed their first field trial in North American using the Meridian 1 Integrated Services Digital Network (ISDN) Q.Sig interface with Lucent's Definity Generic 3 IS Version 4 system.

The Meridian 1 to Definity ISDN Q.Sig interworking trial over a Primary Rate Interface (PRI) has been completed using the International Standards Organization (ISO) protocol specification and included the following ISDN Q.Sig compliant elements:

- Q.Sig Basic Call Services
- Q.Sig Generic Functional (GF) Protocol (Transport)
- Q.Sig Name Display Services (see expanded elements listed below).

Currently, the Definity PBX does not support Q.Sig Call Completion, a Ring Again type feature. However, the Meridian 1 does support the Q.Sig Call Completion Supplementary Service.

Monitored Shipment

ISDN Q.Sig is in a “Monitored Shipment” status at this time because Lucent's Definity is the only PBX vendor to complete an interworking trial with the Meridian 1 in North America. Patches are required for any Meridian 1 to Definity interworking. Please contact your Technical Assistance Support organization prior to any connectivity to a Lucent Definity.

Any additional interworking trial requests to other ISDN Q.Sig compliant PBXs will be reviewed on a case-by-case basis.

Please refer to the ISDN Q-Sig Interworking Product Bulletin #96049 for further details.

Software Patches

There are two manufactured patches on X11 Release 22.46 software for BV69198 (patch MPLR09888), BV70048 (patch MPLR09784).

NOTE: The Japanese market has an additional manufacture installed patch for BV52403 (MPLR09474) which is specific to that region.

An extra manufactured patch is available for BV67488 (MPLR10254) on the following market release versions (these are indicated in the readme.txt file included with the software):

CALA	NTSK02ACR07
Asia Pacific	NTSK03ACR10
US	NTSK11ACR10
Canada	NTSK12ACR10
Japan	NTSK15ACR11
Australia/NZ	NTSK21ACR11

NOTE: Customers currently running 22.46 with two manufacture installed patches can load the version with three patches using the keycode used to enable their initial version of 22.46. This version is available on the Internet for supported regions.

Other patches (if any) which need to be installed must be placed in the following directory on drive C: c:/u/patch

All Option 11C patch files exist in the Global Patch Database. All patch files for the 11C should be placed in the following directory: c:/u/patch. There are 5 ways to get a patch file into this directory.

- 1** Patches can be downloaded to the switch by FTP over an ethernet connection.
- 2** Patches can be downloaded to the switch by FTP over a serial line using SLIP.
- 3** Patches can be downloaded to the switch by FTP over a serial line using PPP.
- 4** Program the patch file onto a PCMCIA card. Install the PCMCIA card in drive a. In pdt copy the patch file from the PCMCIA card to the c drive. e.g.: cp a:newpatch.p c:/u/patch/newpatch.p
- 5** Patches can be downloaded to the switch using XMODEM file transfer over a serial line.

The following is the description of the pdt commands to **perform a file transfer using the XMODEM protocol**.

rx - command for receiving a file

sx - command for sending a file

To use rx, PDT Level 1 or Level 2 password login is required. To use sx, PDT Level 2 password login is required. This is done for security purposes so that you can't get any data out of the system unless you know the PDT Level 2 password.

To transfer a file from a PC/workstation to the switch

```
pdt> rx [path/]filename.ext
```

You then enter the appropriate commands to invoke xmodem file transfer on the PC/workstation

To transfer a file from the switch

```
pdt> sx [path/]filename.ext
```

Enter the appropriate commands to invoke xmodem file transfer on the PC/workstation. For binary files (e.g., patch files and database files), please ensure that the files are transferred in binary mode. When the transfer is completed, a transmission summary is displayed and the pdt prompt is shown.

```
total packets: 20
number of retries: 0
receive timeouts: 1
system errors: 0
unknown characters: 0
transfer cancelled: 0
packets received out of sequence: 0
packets with corrupted sequence: 0
packets failed checksum/crc check: 0
incomplete packets: 0
duplicate packets: 0
```

The following is an **example in a unix environment**:

Use tip to connect to the switch (if you telnet to the switch you can't use umodem).

To transfer a patch to the switch:

```
in pdt
cd c:/u/patch
rx newpatch.p
```

When the system prompts “Ready to receive...”, invoke local command mode by typing ~C (tilde C) and issue the u**m**odem (s)**e**nd (b)**i**nary command.

```
~C      (tilde C to enter local command)
umodem -sb ~mydir/patches/newpatch.p
```

To transfer a file to the workstation

```
in pdt
cd to directory  e.g. c:/p/sl1
sx direct.rec
```

When the system prompts “Ready to send...”, invoke local command mode by typing ~C (tilde C) and issue the u**m**odem (r)**e**ceive (b)**i**nary command.

```
~C      (tilde C to enter local command)
umodem -rb ~mydir/backup/direct.rec
```

The following is an **example in a PC/Window 95 environment**:

Use the HyperTerminal application to dial up to the switch.

To transfer a patch to the switch

```
in pdt
cd c:/u/patch
rx newpatch.p
```

When the system prompts “Ready to receive...”, invoke file transfer on the PC side using the (T)**r**ansfer pull-down menu and selecting the (S)**e**nd File option. Select the file to be sent and select X**M**ODEM as the Protocol. Then start the transfer on the PC side.

To transfer a file to the PC

```
in pdt
cd to directory  e.g. c:/p/sl1
sx direct.rec
```

When the system prompts “Ready to send...”, invoke file transfer on the PC side using the (T)ransfer pull-down menu and selecting the (R)ecieve File option. Select or create a file to be received as and select XMODEM as the Protocol. Then start the transfer on the PC side.

Patch Installation Steps:

1) In pdt use the pload command to load the patches. To make sure that these patches remain in service you must enter the pload command without the patch name. It will then prompt you for the patch name and ask the following questions:

Days patch vulnerable to sysload [3] - set this to 0

In-service initialize threshold [5] - enter a carriage return

In-service days to monitor inits[7] - set this to 0

2) After using the pload command use the pins command to put the patches in service.

Chapter 2 — Documentation

**IMPORTANT: Option 11C documentation library NOW AVAILABLE on CDROM.
Product Order Code: NTDK76AA CPC: A0682476**

CDROM Set includes the following NTP's:

- Option 11C Documentation Package
- X11 Input/Output Guide
- Planning and Engineering Guide
- Meridian X11 Data Features
- ISDN X11 Networking Features
- ISDN Basic Rate Interface Manual
- Generic X11 Automatic Call Distribution
- X11 Software Features Guide
- and more.

The Option 11C documentation has the same format as Option 11E. This chapter describes the new documentation codes for Option 11C for North American (English & French) versions. For other languages, please refer to the regional price book.

Documentation Structure

Documentation is packaged as:

- Base package
- Optional documents

Base Package

Table 2: Base Package Codes

NT Code	CPC Code	Region	Binding	Language
NT6R78AA	A0654626	North American	Coil	English
NT6R77AA	A0654624	North American	Binder	English
NT6R78BA	A0654627	North American	Coil	French

Table 3: Contents of North American English/French Base Package - Coil

Title	English	French
Read Me First Handbook	P0833301	P0835296
Installation Guide	P0833302	P0835306
Fault Clearing Guide	P0833297	P0835287
Software Installation Menu	P0833303	P0845232
Central Answering Position	P0835240	P0835268
Customer Configuration backup and restore Guide	P0835273	P0835276
Upgrade Procedure	P0833305	P0835322
X11 Software Guide	P0835516	P0835544

Table 4: Contents of North American English Base Package - Binder

Title	English
Overview, Installation, and Programming	P0835301
Post Installation Activities	P0835317
X11 Software Guide	P0835548

General information and planning-Read me first Handbook

Contains the contents of the former Read me first booklet plus new high-level information:

- Overview of the Option 11C
- Equipment Identification
- System and site requirements
- Regulatory and other information
- Important safety instructions
- Bracing cabinets against earthquakes

Installation guide

This guide outlines the process of installing a new Option 11C main cabinet system and expansion cabinets, if required. If you are upgrading an existing Option 11 or Option 11E system to an Option 11C, refer to the Upgrade Procedures Guide.

Fault clearing guide

This guide contains information required to maintain, clear faults, and replace defective components in the Option 11 system.

Software Installation Program Guide

This guide contains information required to use a menu-driven method of selecting from the various options for installing, modifying, or upgrading the software, customer data, and ISM parameters.

Central Answering Position guide

This guide contains information on how to configure and use a regular business telephone as a Central Answering Position in lieu of an attendant console. It includes:

- A description of what the CAP is and a list of the required equipment.
- Procedures for configuring the CAP.
- Procedures for installing and removing key expansion modules.
- Procedures for logging onto the ACD queue.
- A description of the common CAP features, including step-by-step procedures on how to use these features.

Customer Configuration Backup and Restore guide

This document describes the Customer Configuration Backup and Restore feature. It contains information about Option 11 and computer equipment requirements and includes instructions on how to operate and use the feature from a remote location and on-site.

Upgrade procedures

This guide contains information required to upgrade an existing Option 11 or Option 11E system to Option 11C system. It also includes procedures for upgrading an existing Option 11C software to a new release.

X11 software guides

These books show the prompts and responses in each of the overlay programs and list maintenance and administration messages.

Optional Documents

Table 5: Optional Documents English/French - Coil

Title	English	French
Technical Reference Guide	P0837650	P0837651
1.5 Mb DTI/PRI Guide	P0837630	P0837631
2.0 MB DTI/PRI Guide	P0837637	P0837638
BRI Guide	P0837643	P0837644
X11 Software Feature Guide (Rls 22)	P0842661	
Distributor Technical Library (contains X11 Software feature guide, Option 11C Technical reference guide, Option 11C GRB, & System security guide)	A0670815	

Chapter 3 — Features Overview

This section provides a summary of the new features and enhancements included in X11 Release 22. For more information on these features, refer to the documents listed under “Document References.”

Platform Evolution

68040 Call Processor For Options 51C/61C

This feature is an enhancement of the new 68040 product introduced in Release 21 for the Option 81/81C to support the Option 51C and 61C systems. The 68040 is a new processor pack which improves real time performance over the existing processor pack, the 68030. The 68040 uses the 68040 processor whereas the 68030 uses the 68030 processor. 68040 operations, features and functionality on Option 51C/61C are the same as for 68040 on Option 81/81C.

No new software package is introduced by this feature.

E.164/ESN Numbering Plan Expansion

CCITT (the International Telegraph and Telephone Consultative Committee) is mandating (recommendation E.164) that the capability of supporting 15 digit numbering plans be available and in effect by December 31, 1996 11:59 PM Universal Standard Time (Time T) for Integrated Services Digital Network (ISDN) and Public Switching Telephone Network (PSTN) dialing. The basic change is the mandate to support up to 15 digit International numbers versus the present dialing plan which supports up to 12 digit International numbers.

This development will affect 4 fundamental areas:

- a** Screening digits as they relate to the Special Number Translation (SPN)
- b** Numbering Plan modifications as they are mandated by CCITT
- c** An enhancement to Supplemental Digit Restriction and Recognition (SDRR)
- d** The capability to outpulse 31 digits in our current feature offerings.

A summary of changes follows:

<u>ESN Changes</u>	<u>OLD</u>	<u>NEW</u>
Max number of digits for an SPN	11	19
Max number of DMI deletion digits	15	19
Max number of DMI insertion digits`	24	31
Max number of SDRR tables with Bars	256	1500
Max number of SDRR tables with Nars	512	1500
Max number of digits in each SDRR entry	7	10
Max FNP FLEN number for SPN	16	24
Max number of digits for the FSNS SPN	11	19
Total number of digits for screening under FSNS	14	22
Number of possible SDRR entry types	8	9
Restriction for SDRR entry codes	Leftwise unique	None

<u>ISDN Changes:</u>	<u>OLD</u>	<u>NEW</u>
BRI Basic Call Service (BRIL)	24	31
Called Party IE for QSig Interface	24	31
Called Party IE for EuroISDN Interface	20	31
BRI Call Forward for NI-1 Standard	20	31
BRI Call Forward for ETSI Standard	20	31
Max OVLL digits	16	24

<u>Base Feature Changes:</u>	<u>OLD</u>	<u>NEW</u>
Max number of digits for ADL entry	23	31
Max number of digits for NHC target DN	23	31
Max number of digits for CFAC DN	23	31
Max number of digits for Internal CFW DN	23	31
Max number of digits for default CFW DN	23	31

No new software package is introduced by this feature.

Station Features

Call Redirection by Time of Day

This feature provides automatic redirection of an incoming call to a predefined DN depending on the time of day. Alternate time options are defined at the customer level in Overlay 15, with four alternate time options available per customer. The feature is then activated/deactivated on a per set basis in Overlays 10 and 11.

Call Redirection by Time of Day applies to: Hunt, Call Forward No Answer, and Call Forward / Hunt by Call Type.

No new software package is introduced by this feature.

Meridian Mail Password Suppression

Meridian Mail Password Suppression provides a new AML message which will prevent a Meridian Mail user's log on password digits from being echoed on a set's display.

No new software package is introduced by this feature but Meridian Mail Release 11 is required.

Flexible Feature Code Enhancements

This program comprises four feature developments:

- Call Forward Deactivation
- Called Party Control on Internal Calls
- Automatic Wake-up Delimiter
- Speed Call Delimiter

Call Forward Deactivation: This feature allows the receiver of forwarded calls to deactivate call forward to their DN. No special password is required. Example,

Set A (DN 2000) forwards to set B (DN 3000). Set B dials
CFDD FFC + DN 2000 + #
Result is that Set A is no longer forwarded to Set B.

No new software package is introduced by this feature.

Called Party Control on Internal Calls: This feature allows Called Party Control of a call if MCTA is configured on the station. Until the called station disconnects, the call remains “up”. Any disconnect treatment, such as Tone to Last Party, will not occur until the called station disconnects. If the calling party attempts to disconnect, the called station is put on hold. The called station can activate MCT any time up until they disconnect. This feature applies to internal calls only, and no activation by the user is required.

This feature requires a new package Called Party Control on Internal Calls (CPCI) package 310 and also requires Malicious Call Trace (MCT) package 107.

Automatic Wake-up Delimiter: A customer level option which allows the entry of an EOD delimiter at the end of the AWUA entry string. Example,
AWUA FFC + H1H2M1M2 + #

No new software package is introduced by this feature.

Speed Call Delimiter: A system level option which allows the speed call controller to now enter a delimiter in the programmed number string. Example,

SPCC FFC + speed call entry number + * (**delimiter**) + number to be dialed + #

No new software package is introduced by this feature.

Networking Features

ISDN QSig Basic Call (for 1.544 Mb PRI)

The initial offering of the QSig product supports basic call service plus other basic functions such as Calling Line Identification Presentation / Restriction (CLIP/CLIR) and Connected Line Identification Presentation / Restriction. This feature provides the basic call services on M1 ISDN 1.544 Mbps PRI on QSIG connectivity.

This feature requires a new package, QSIG Interface (QSIG), package 263.

Call Park Networkwide

Call Park Networkwide adds three new functions to Call Park:

1. Call Park Expansion
2. Network Call Park
3. Parked Call External Access

Call Park Expansion: Previously, the Call Park feature allowed each customer to have only one call park block. This new function will allow each customer to now have:

- up to 5 call park blocks
- unique attributes per block (i.e. recall timer, recall to Attendant option, number of system park DNs, first system park DN, and Music route)
- maximum Call Park recall time in each block increased from 240 to 480 seconds
- maximum number of System Park DNs expanded from 50 to 100 per block

Network Call Park: Previously, a call could only be parked by a parking party onto a station DN or a System Park DN that is on the same node as the parking party. The Network Call Park function provides the parking party an option to park a call onto a station DN or a System Park DN located at any Meridian 1 node within the same MCDN NAS network as the parking party. ROSE protocols are used for message encoding, and D-channels are required to support the Network Call Park feature.

Parked Call External Access: Previously, a parked call could only be accessed by an Attendant Console or telephone set located at the same node as the parking party. The Parked Call External Access function allows a call that is parked on a System Park DN to be retrieved by an outside caller via,

- ESN dialing, if within the private network, or
- DID dialing if calling from external resources

This feature requires a new package, Call Park Network Wide (CPRKNET) package 306.

Call Page Networkwide

Previously, paging routes could only be accessed by an internal Attendant Console via a Page key or route ACOD dialing, or by an internal telephone set via route ACOD dialing. This feature development will now allow an outside caller to access the paging route via ESN dialing. Additionally, Call Page Networkwide will provide an optional security protection. Service change will enable the system administrator to define a paging route as “Network Access Restricted”, allowing external access only by an Attendant Console, or “Network Access Allowed”, allowing external access by a set as well. Service change will also be at the set level, with a new class of service to allow or deny access to Call Page Networkwide.

Internal access to paging will not be affected by this feature, and will function as it does today. The intent of this feature is to support all Bars/Nars and CDP dialing for network page access.

This feature requires a new package, Call Page Network Wide (PAGENET), package 307.

ISDN CLID Enhancements

This feature enhances the Meridian 1 ISDN CLID networking capabilities in private and public ISDN networks. Enhanced capabilities include:

- allowing virtually any number to be programmed against any DN key on a per set basis
- allowing any LDN/dept LDN to be used on a per DN key, per set basis• supporting
- supporting multiple HNXX and location codes
- supporting 2-3 / 5-7 digit DNs
- generating CLID on incoming analog/DTI/ISDN trunks
- allowing users to program DISA DN to use a specific LDN or use the CLID arriving from the public ISDN Network.

No new software package is introduced by this feature.

ISDN QSig GF Transport

This development provides generic functional transport services over ISDN trunk interfaces for the support of ISDN supplementary services and networking applications. It is based on the ISO DIS 11582 and ETS 300 239 specifications, and supports three types of GF Transport services to the control entities:

- call related APDU transport - provides transport of supplementary service protocol information in association with a basic call
- call related notification transport - used to deliver additional information to an ISDN end user in association with a basic call
- call independent APDU transport - used for the transport of supplementary service protocol information which is entirely independent of any existing basic call (e.g. call forward).

ISDN QSig GF Transport also provides an MCDN conversion platform to allow migration of current MCDN features to the QSig GF platform. However, this protocol converter does not automatically support current MCDN features on the QSig network. Each MCDN feature will have to be individually ported to the QSig interface in the future.

This feature requires a new package, QSIG GF Transport (QSIGGF), package 305.

ISDN QSig Supplementary Services - Call Completion

This feature provides the Call Completion supplementary services: Call Completion to Busy Subscriber (CCBS), and Call Completion on No Response (CCNR).

The CCBS supplementary service allows a user placing a call to a busy extension to apply Ring Again against the busy extension. The calling party is alerted when the busy extension becomes free, and can have the call completed without having to make a new call attempt. The user operation is similar to the current NRAG feature (MCDN Network Ring Again). CCBS is supported for QSig protocol.

The CCNR supplementary service allows a user placing a call to an idle extension to apply Ring Again against that extension if the call is not answered. The calling party is alerted after a subsequent period of activity, and can have the call completed without having to make a new call attempt. CCNR is only supported at the Q reference point for QSig.

This feature requires a new package, QSIG Supplementary Services - Call Completion (QSIG-SS), package 316.

ISDN QSig Supplementary Services - Name Display

Name Display services consists of three components: Calling Name ID Presentation (CNIP), Connected Name ID Presentation (CONP), and Calling/Connected Name Restriction (CNIR).

CNIP is a service offered to the called party, and provides that user with the calling party's name. CONP is a service to the calling party, and provides that user with the connected party's name. CNIR is a service which prevents the called user's name from being presented to another user. It can apply to all calls, or can be invoked on a per call basis. CNIR can restrict the presentation of the called user's name not only during normal call establishment, but also when the possibility of name presentation arises during the operation of other Supplementary Services.

This development will also enhance the MCDN name display feature to have a similar level of service as the QSig Name Display services, and to provide Incoming Digit Conversion (IDC) trunk name, when available.

Both the QSig and MCDN gateways will be supported by this feature.

No new software package is introduced by this feature.

VNS / VDN Expansion

Currently, the VNS feature uses virtual DNs (VDN) to set up bearer calls. The number available per customer is equal to 100 consecutive DNs. This means that up to 100 simultaneous VNS calls (incoming and outgoing) can be supported on the Meridian 1.

This development will expand the available DNs for VNS to 4000, and will allow those to be configured on an individual rather than consecutive basis.

No new software package is introduced by this feature.

Trunk Anti-Tromboning

Trunk Anti-Tromboning (TAT) was developed on X11 Release 21.35 and later software to eliminate tromboning PRI B-Channels, ISL trunks, or VNS trunks due to call redirection (e.g. call forward or hunt) or call modification (e.g. call transfer or conference) between two Meridian 1 switches, or between Meridian 1 and DMS switches equipped with Release Link Trunks. It operates over ISDN PRI, ISL, or VNS networks.

An example of TAT follows:

Set B receives an incoming PRI call from Set A, or an incoming CO is tandemed to the terminating node. Set B answers the call, then activates network call transfer to Set C located at the originating node. Set B completes the call transfer, leaving Set A connected to Set C using PRI trunks. Set C answers the call. The call between Sets A and C will be cut-thru at the originating node, and the tromboning PRI trunks will be removed.

This feature introduces a new package, Trunk Anti-Tromboning (TATO), package 312.

Display of Calling Party Denied

Display of Calling Party Denied (DPD) was developed on X11 Release 21.35 and later software and permits Analog (500/2500 type) and Meridian 1 proprietary sets to either allow or deny associated name and number from being displayed on other sets when involved with a call. This feature is supported on internal calls (same node) and calls placed over a Meridian Customer Defined Network (MCDN) Integrated Digital Services Digital Network (ISDN). Display of Calling Party Denied Class of Service Options are programmed on a set basis.

No new software package is introduced by this feature.

Trunk-to-Trunk Connections

This development addresses four functions/areas. First, it will allow the transfer on ringing of an established external trunk call over a supervised network trunk. To ensure that available network resources are not tied up indefinitely, if the called party does not answer within a specified time, then the call will slow-answer-recall to the attendant on the transferring node.

Second, it will allow the connection of one outgoing external trunk to another via call transfer, as long as both of the external trunks are supervised.

Third, this development will allow external trunks to remain established in a conference call once the internal set disconnects, if all the external trunks involved offer disconnect supervision.

No new software package is introduced by this feature.

Fiber Remote IPE Phase II

Fiber Remote IPE Phase I was developed independently of software, compatible back to Release 19. It introduced the Fiber Remote IPE hardware, and an MMI connected directly to the hardware.

Phase II will consist of new service change capability for configuring remote FIRE systems, peripheral software download of the FNET and FPEC, and download of various operating parameters including time and date. Also, maintenance of the cards and fiber link will be provided, including:

- enable/disable FNET and FPEC
- enable/disable optical packets
- card selftest and optical packets test
- manual continuity tests
- print event and error messages according to cards' report
- read the log file of the cards to track history of problems
- print link's performance monitoring report upon demand.

Also, the loadware of the FNET and FPEC will be modified to report alarms and events to the software, in addition to the printouts on the MMI port.

No new software package is introduced by this feature.

Call Center

Meridian Link Release 5

Meridian Link Release 5 introduces the following new features:

1. Enhanced reporting of call release - provides information as to why a call was disconnected. This reporting will occur for abandoned calls only.

2. Hold/Unhold - allows the hold feature to be activated through the Meridian Link. When the host application sends out a Hold Request message, the result is equivalent to depressing the hold button on a BCS set, or flashing the switchhook on a PBX set. The cancellation of the hold is done by the Retrieve Original message, which is also enhanced to support PBX sets.

3. Additional ISDN progress messages for outbound calls - currently, Meridian Link receives only ringing and busy progress messages for outbound calls. This feature will provide several specific values identified from the ISDN cause IE values to be sent to the application. The values are: 1 unallocated; 3 no route to destination; 17 user busy; 18 no user responding; 22 number changed; 27 destination out of order; 28 invalid number format; 34 no circuit/channel available; 38 network out of order; 41 temporary failure; 42 switch equipment congestion; and 127 interworking unspecified with inband information available.

No new software package is introduced by this feature.

System Enhancements

Network Authorization Code (NAUT)

This enhancement is introduced with Release 22.37 software.

The Network Authorization code feature enables selected users to temporarily override the access restrictions assigned to a station or trunk. A user can enter an authorization code to access more of the system facilities than would normally be allowed to the particular station or trunk because of the assigned NCOS (Network Class of service), COS (Class of service) and TCOS (Trunk group access restriction). The NAUT feature provides up to 20,000 authorization codes of 1 to 14 digits (with Release 13 and later).

Enhanced functionality:

When an Authorization code is used to place an outgoing call and a conference call is made to a second outgoing call, then an Authorization code is required. This generates CDR for the second call involved.

A new prompt 'NAUT' in LD 15 is provided in the FTR_DATA of the Customer Data Block. If the input for 'NAUT' is NO, the existing functionality is maintained. If the input for 'NAUT' is YES, then the user is prompted for an authorization code entry. LD 21 is also modified to print the new prompt 'NAUT'.

The user is prompted for an authorization code entry only if the Facility Restriction Level associated with the NCOS of the incoming (or two-way) tie trunk is less than the minimum FRL of the route list that NARS, BARS, or CDP would use for the call. In addition if the user is at a remote switch, the user may be prompted for the authorization code entry if the route is defined in the Route Data Block to prompt for an authorization code entry on incoming NARS, BARS or CDP calls. If using DISA, the user is prompted for the code entry if the FRL of the NCOS assigned to the DISA DN is less than the Minimum FRL of the route list that NARS, BARS or CDP would use for the call.

- With 'NAUT' set to YES in the Customer Data Block, Authorization code is reprompted for Call Transfer and Conference.
- With 'NAUT' set to YES in the Customer Data Block, Authorization code is reprompted when accessed through the DISA feature.
- With 'NAUT' set to YES and OPT set to Call Forward Forwarding Originating (CFO) in the Customer Data Block, a caller may be prompted for an authorization code entry after a call to a station that forwards the call to NARS, BARS or CDP number.
- With 'NAUT' set to YES and OPT set to Call Forward Forwarding (CFF) in the Customer Data Block, the user will not be prompted for an authorization code on making a call to a station that forwards the call to NARS, BARS or CDP number.
- With 'NAUT' set to YES in the Customer Data Block, CDR is generated for both trunks involved.
- With 'NAUT' set to YES/NO in the Customer Data Block, an attendant is reprompted for an authorization code entry if the FRL required to access a route list for a NARS, BARS or CDP call is greater than the FRL of the attendant's NCOS.

The Network Authorization code will be prompted only if it is configured (in LD 88). Reference: BV37132

Call Forward/Breakin/Hunt Internal & External Networkwide

This feature determines whether a call is internal or external on a network wide basis. A call should be treated as internal if it both terminates and originates within the private network. The available information (Numbering Plan Identifier[NPI] in the CLID, or NAS for MCDN) associated with a call is decoded to choose between different treatments for Break-In Indication Prevention, Call Forward by Call Type, or Hunt by Call Type.

If neither the CLID or NAS information is present, the route class mark defined in the route data block at the treating node will be used to determine if the call should be treated as internal or external. With QSig, the CLID and NPI information will be used. If it is not present, then the QSig specific data giving information on the far end of the call will be used.

No new software package is introduced by this feature.

M2216 ACD Set Voice Parameters

This feature will allow an increase of 6dB when downloading voice parameters to the M2216 sets, instead of using general ROLR values. In addition, a specific Receive Objective Loudness rating will be able to be configured for M2216 sets. The purpose of these changes is to correct reported transmission problems for M2216 sets when using a headset.

No new software package is introduced by this feature.

Meridian Mail Trunk Access Restriction

This feature will prevent direct or indirect call transfer or conference of external calls to Meridian Mail by 500/2500 and BCS sets. An external caller may be transferred or conferenced to Meridian Mail by the Attendant. This option will be configurable at a customer level.

No new software package is introduced by this feature.

CDR 100 Hour Call

This feature removes the current CDR limitation of the inability to record calls exceeding 99:59:59. A new three digit field will be created representing CDR duration hours in hundreds, thousands, and ten thousands. In effect, this will increase the maximum CDR duration to 99999:59:59.

The new field will be located on the third line of the Global CDR record with the following format (as an example):

&00:15N00:25 BLID M911 001

The format translates:

Indicate 3d line of TTY:Time to answer Billing line ID M911 call
abandon 100th hour

No new software package is introduced by this feature.

Flexible Voice/Data TN

The initial application involves the VISIT product only. Note that existing BCS sets will not be able to use these new capabilities.

This feature will now allow each TN (channel) on an XDLC to be assigned as either voice or data on a dynamic (per call) or static basis. This will allow Visit Video to utilize the entire bandwidth of a TCM loop for video conferencing, using both channels as data. Visit also plans to offer simultaneous voice and fax on a single TCM loop using both channels as voice.

No new software package is introduced by this feature.

Init ACD Queue Call Restore

The existing system initialization process rebuilds calls that have reached the established state only, based on the content of the control memory. The Init ACD Queue Call Restore (ACDR) feature enables the Meridian 1 to restore transient calls in the ACD queues in the event of a system initialization. The following parameters apply:

- only trunk originated calls will be restored
- virtual calls will not be restored (e.g. Ntwk ACD call requests queued at target ACD-DNs)
- maximum of 1000 calls will be restored.

A special 16K of unprotected memory will be allocated for ACDR usage.

No new software package is introduced by this feature.

System Access Enhancements (SAE)

This development will provide enhancements to Meridian 1 system access for OA&M System Security and Toll Fraud Prevention. The enhancements cover the following seven areas.

SAE will limit the number of invalid attempts to access/enter PWD2 and LAPW in Overlays 15, 17, 21, 22, and 24. In addition, the system will perform corrective actions when the number of invalid login attempts exceeds the maximum threshold.

SAE changes the current default Class-of-Service value from UNR to CTD. This change will impact Overlays 10, 11, 14, 16, and 27.

SAE changes the current default TGAR/TARG value from “0” to “1”. TGAR is changed for Overlays 10, 11, 14, 24, 27, and 88. TARG is changed for Overlay 16.

SAE will allow a Call Forward (All Calls) DN length to be any number in the allowable range from 4-23 digits. Also, the default length is changed from 16 to 4 digits.

SAE changes the commercial processors' PDT password from a fixed, unchangeable password to a system unique password of 6-12 characters. The password will be encrypted in a file that can be changed by the user with the highest password access level (unlimited system access).

SAE will store LAPW passwords and Login Names contiguously in an encrypted rather than unencrypted file format.

SAE will allow a user to configure an option to display a security banner in Overlay 17 when USER is defined as MTC or SCH.

No new software package is introduced by this feature.

OA & M**Alarm Management**

Alarm Management is comprised of a series of sub-features developed to improve the handling of key alarm messages generated by the Meridian 1.

Event Handling

The current system History File content is lost after a sysload. With this development, a new disk-based log file, the System Event Log, will survive any sysload, initialization, or power failure. Users can browse the System Event Log through a new Overlay # 117.

The Event Server is required for all Option 11C, 51C, 61C, 81, and 81C machines. It provides an Event Default Table which appends messages with severity. The server also provides an Event Preference Table which contains site-specific preferences for event severities, as well as criteria for severity escalation.

Alarm Notification

The Major Alarm LED on the attendant console is lit when a power failure occurs. This function of the Major Alarm is preserved. However, for the Minor Alarm, all existing procedures which call for the Minor Alarm lamp to be lit are removed. The Minor Alarm lamp will now be lit from a central location based on alarm severity. There will be three alarm categories: critical, major, and minor. The minor lamp on the attendant console will now light when a critical alarm occurs. The severity of the Minor Alarm is determined by the Event Server.

Alarm Clean-up

The Meridian 1 currently generates some alarms that may be incorrectly reported, or that do not indicate the source of the fault. This feature improves the message content and/or consistency of these alarms. These alarms are centralized to ensure their capture under the new Event Handling mechanism. This functionality is applicable to all system types supported in Release 22.

No new software package is introduced by this feature.

SMP Platform

This development comprises two sub-features: Point-to-Point Protocol and Ethernet Productization.

Point-to-Point Protocol

Point-to-Point Protocol (PPP) provides a standard encapsulation scheme to transmit Internet Protocol (IP) datagrams over a serial link. Only asynchronous data link is supported. PPP also provides the communication interface for NT applications to perform administration and maintenance tasks. Therefore, the SDI port used for the PPP link must be configured for maintenance (MTC) and/or service change (SCH). In addition, the Meridian 1 must be configured as follows:

- baud rate is limited to the type of hardware the SDI port can provide
- 8 data bits, 1 stop bit
- no parity
- transmission mode set to DTE
- standard RS-232C interface

Due to the complexity of the modem types, only Hayes and Hayes AT command compatible modems are supported.

Ethernet Productization

This feature provides an interface for NT developed applications to communicate with the Meridian 1 over an Ethernet connection. This connection is reserved for NT connected applications.

An Ethernet address, which is a unique physical address, is assigned to the Ethernet controller equipped in the IOP. On a redundant M1 system, there are two IOPs, therefore two Ethernet addresses. However, both IOPs should be set to use only one Ethernet address for communication over the link.

An IP address, which is manually configured by the user, is associated with a host name. On a redundant M1 system, two IP addresses and host names, one primary and the other secondary, must be specified. The primary IP address is always the address used by the system. The secondary IP address is used only when the system is operating in split mode.

To communicate over the Ethernet link, the M1 system must be configured with both an Ethernet address and an IP address.

No new software package is introduced by this feature.

Maintenance Windows

Meridian Administration Tools (MAT) provides a number of Microsoft Windows applications to help users manage the Meridian 1. Maintenance Windows is a set of MAT applications being introduced with Release 22 for Windows 95 that requires MAT Release 5.x.

Maintenance Windows provides three new MAT applications.

Meridian 1 Equipment Views - provides a GUI replacement for the overlay-based hardware maintenance commands. An equipment view window contains a list of M1 hardware objects, such as network loops. The user can select an item in the list and choose a maintenance command from a pop-up menu. Only the commands appropriate for the selected object are displayed in the menu.

Event Monitor - provides a window for viewing M1 system error messages. In MAT, these messages are called 'events'. Each event has a severity of critical, major, minor, or information. Events with a severity of critical, major, or minor are considered events. The user can acknowledge and clear alarms, filter out selected alarms and events, view help on each event, and modify the Event Preference Table.

Overlay Passthru - provides on-line, context sensitive help for the existing overlay based user interface.

This feature requires two new packages, Open Alarms (OPEN ALARM), package 315 which depends on Meridian Administration Tools Management Interface (MAT_PKG), package 296.

Chapter 4 — Overlays

The following table summarizes the status changes of the administration overlays on Option 11C, compared to Option 11E.

Table 6: Administration Overlays Status Changes

Overlay	Description	11E	11C
OVL 13	DTRs, DTDs, MF Senders and Receivers	Supported	Modified
OVL 14	Trunks	Supported	Modified
OVL 17	Configuration Record 1	Supported	Modified
OVL 25	Move Data Blocks	Supported	Modified
OVL 29	Memory Management	Supported	Unsupported
OVL 97	Configuration Record 2	Supported	Modified
OVL 117	Alarm Management and Network Configuration	Unsupported	Supported

Administration Overlays

Overlay 13

This overlay has been modified to add 8 more XTD/DTR units (8-15) on card 0 or 4 MFC/MFE/MFR/MFK5/MFK6 units (8-11) on card 0.

Overlay 14

This overlay has been modified to add trunk level transmit level identifier. MFL prompt in overlay 14 is not supported for Option 11C.

Overlay 17

New prompts have been added to this overlay to allow for configuration of the new TTY ports introduced on Option 11C. Prompts are also added for defining flow control for the TTY ports.

The additional conference loop for Option 11c is configured automatically at sysload for an upgrade, however this overlay has been modified to allow manual removal and configuration of this additional conference loop.

Overlay 25

This overlay has been modified to add restriction for moving card 0.

Overlay 29

Not supported on Option 11C

Overlay 97

This overlay has been modified to allow two system level multifrequency transmit level identifiers.

Overlay 117

This overlay is now supported for Option 11C.

The following table summarizes the status changes to all maintenance and diagnostic overlays on Option 11C, compared to Option 11E.

Table 7: Maintenance and Diagnostic Overlays Changes

Overlay	Description	11E	11C
OVL 7	Enhanced Maintenance	Supported	Unsupported
OVL 8	Debugger	Supported	Unsupported
OVL 9	Debugger	Supported	Unsupported

Table 7: Maintenance and Diagnostic Overlays Changes

Overlay	Description	11E	11C
OVL 32	Network and Peripheral Equipment Diagnostics	Supported	Modified
OVL 34	TDS and DTR Diagnostics	Supported	Modified
OVL 38	Conference Circuit Diagnostics	Supported	Modified
OVL 54	Multifrequency Signalling Diagnostics	Supported	Modified
OVL 135	Core Common Equipment Diagnostics	Unsupported	Modified
OVL 137	Core Input/Output Diagnostics	Unsupported	Modified
OVL 143	CCBR and upgrade	Unsupported	New
RESDB	Resident debug	Supported	Unsupported

Maintenance and Diagnostic Overlays

Overlay 32

This overlay is modified to support extended tone services units on the CPU card.

Overlay 34

This overlay has been modified to support tone services units which can now be defined as different types on the CPU card.

Overlay 38

This overlay has been modified to support a new conference loop which is provided with the second expansion cabinet on the Option 11C.

Overlay 54

This overlay has been modified to support MFC/MFE/MFK units on Card 0. Some of the functionality has also been moved to Overlay 34.

Overlay 135

Several new commands have been added to this overlay to support Option 11C fiber interface maintenance.

Overlay 137

Many commands in this overlay are not supported on Option 11C.

Overlay 143

This overlay has been introduced to invoke the Option 11C Installation program. The customer configuration backup and restore (CCBR) commands have been moved from Overlay 43 to this new overlay.

For more details on specific changes, refer to X11 Release 22 Software NTPs.

Chapter 5 – Software Packaging

Software Options and Package Dependencies

Please note that for software packages introduced prior to Release 20, dependencies within dependencies are not listed. However starting with Release 20, dependencies within dependencies are listed in some cases for new software packages.

Note: Packages which are not supported on any machine type are not included in this table

Table 8: Software Package Dependencies

Pkg #	Mnemonic	Name	Package Dependency	Comments
0	BASIC	Basic call Processing		
1	OPTF	Extended PBX Features		
2	CUST	Multiple Customer Operation		
4	CDR	Call Detail Recording		
5	CTY	CDR on Teletype Machine (TTY)	CDR-4	see pkg# 5, 24, 83, 108 Without pkg#5 CDR cannot output statistics or reports
7	RAN	Recorded Announcement	INTR - 11	
8	TAD	Time and Date		

Table 8: Software Package Dependencies

Pkg #	Mnemonic	Name	Package Dependency	Comments
9	DNDI	Do Not Disturb Indiv		
10	EES	End to Ens Sig.		
11	INTR	Intercept Treatment		
12	ANI	Auto. Number Ident.		
13	ANIR	ANI Route Selection	ANI - 12	
14	BRTE	Basic Routing	NCOS-32	
15	RPE	Remote Peripheral Equip.		Not supported on 11/11E/11C
16	DNDG	Do Not Disturb Group	DNDI -9	
17	MSB	Make set Busy		
18	SS25	2500 set features		
19	DDSP	Digit Display		
20	ODAS	Office Data Admin. System		
21	DI	Dial Intercom		
22	DISA	Direct Inward System Access		
23	CHG	Charge account for CDR	CDR -4, CAB - 24	
24	CAB	Charge Account/Authorization		
25	BAUT	Basic Auth. Code	CAB-24	
26	CASM	Centralized Attn. Service (main)		Not supported on 11/11E/11C

Table 8: Software Package Dependencies

Pkg #	Mnemonic	Name	Package Dependency	Comments
27	CASR	Centralized Attn. Service (Remote)		Not supported on 11/11E/11C
28	BQUE	Basic Queuing		
29	NTRF	Network Traffic measurement	BARS-57, NARS-58, CDP-59, PQUE-60, FCBQ-61, OHQ-62	One of Pkg. 57-62 must be equipped
32	NCOS	Network Class Of Service		
33	CPRK	Call Park		
34	SSC	System Speed Call		
35	IMS	Integrated Message service	ACDA-45, MWC-46	
36	ROA	Recorded Overflow Announcement	RAN-7	
37	NSIG	Network Signalling	NCOS-32	
38	MCBQ	Main Network Queuing	NSIG-37, FCBQ-61	
39	NSC	Network Speed Call	SSC-34, BARS-57 or NARS-58	
40	BACD	Basic ACD		see also ACDA-45, ACDB-41, ACDC-42, LMAN-43, ACDD-50, LNK-51, CDRQ-83, TOF-111, DNIS-98
41	ACDB	ACD Package B	ACDA-45	
42	ACDC	ACD Package C1	ACDB-41	

Table 8: Software Package Dependencies

Pkg #	Mnemonic	Name	Package Dependency	Comments
43	LMAN	ACD Load Mgmt. C2	ACDC-42	Mutually exclusive with package 26, 27, or 159.
44	MUS	Music	RAN-7	
45	ACDA	ACD Package A	BACD-40	
46	MWC	Message Center		
47	AAB	Auto. Answer Back		
48	GRP	Group Call		
49	NCFR	Network Flexible Code Restriction	NCOS-32	
50	ACDD	ACD package D	ACDC-42, LNK-51	
51	LNK	Aux. Link Processor	ACDD-50	
52	FCA	Forced Charge Account	CHG-23	
53	SR	Set Relocation		
54	AA	Attn. Administration		
55	HIST	History File		
56	AOP	Attn. Overflow Position		
57	BARS	Basic Alternate Route Selection	BRTE-14, NCOS-32	
58	NARS	Network Alternate Route Selection	14, 32	
59	CDP	Coordinated Dialing plan	BRTE-14, FCBQ-61	
60	PQUE	Priority Queuing	NCOS-32	

Table 8: Software Package Dependencies

Pkg #	Mnemonic	Name	Package Dependency	Comments
61	FCBQ	Flexible Call Back Queuing	BQUE-28, BARS-57 or NARS-58 or CDP-59	Not supported on 11/11E/11C
62	OHQ	Off-Hook Queuing	BQUE-28, BARS-57 or NARS-58	
63	NAUT	Network Aut. Code	BAUT-25, BARS-57 or NARS-58 or CDP-59	
64	SNR	Stored Number Redial		
65	TDET	Tone Detector		
67	NXFR	Network Call Transfer	NSIG-37	
68	ATVN	Autovon		
69	ACDR	Autovon CDR		
70	HOT	Hot Line Services	NCOS-32, SSC-34. Optional Pkgs: ISDN-145, PRA-146/ISL-147, NTWK-148	
71	DHLD	Deluxe Hold		
72	LSEL	Auto. Line Selection		
73	SS5	500 Set Features	SS25-18	
74	DNRG	Distinctive and new Dist. Ringing		

Table 8: Software Package Dependencies

Pkg #	Mnemonic	Name	Package Dependency	Comments
75	PBXI	PBX Interface for DTI	CDR-4, BACD-40	Not supported on Option 11C
76	DLDN	Dept. Listed DN		
77	CSL	Command Status Link		
79	OOD	Optional Outpulsing Delay		
80	SCI	Station Category Indication		
81	CCOS	Controlled Class of Service		
82	RESDB	Resident Debug		
83	CDRQ	ACD CDR Queue Record		
84	ATM	Auto. Trunk maint.		
86	TENS	Mult. Tenant Service		
87	FTDS	Fast Tone and Digit Service	DSET-88	Not supported on Option 11/11E/11C
88	DSET	Digital Sets		
89	TSET	Touchphone sets		
90	LNR	Last Number Redial	DSET-88	
91	DLT2	M2317 Digital Display		
92	PXLT	Pretranslation		
93	SUPV	Sup. Attn. Console		

Table 8: Software Package Dependencies

Pkg #	Mnemonic	Name	Package Dependency	Comments
95	CPND	Call Party Name Display	DDSP-19,DS ET-88,TSET-8 9,ODAS-20 FOR DES, BGD-99	
97	JCO	Japan CO Trunk		
98	DNIS	Dialed Number Ident. service	DDSP-19, ACDA-45, APL-109, IDC-113	
99	BGD	background terminal	RMS-100, 81 - COS, MR-101, AWU-102, PMSI-103	
100	RMS	Room Status	BGD-99, DNDI-9, MWC-46	
101	MR	Message Registration	BGD-99	
102	AWU	Auto. Wake-up	RAN-7, BGD-99	
103	PMSI	Property Mgmt. System Interface	RMS-100	
104	OPAO	Outpulsing of * and #		
105	LLC	Line Load Control		
106	SLP	Station Loop Preemption		

Table 8: Software Package Dependencies

Pkg #	Mnemonic	Name	Package Dependency	Comments
107	MCT	Malicious Call Trace	ISDN-145, PRA-146, or ISL-147, NAS-159, ISDNS-161	
108	ICDR	Internal CDR	CDR-4	
109	APL	Aux. Processor Link		
110	TVS	Trunk Verif. from a station		
111	TCF	ACD Timed Overflow	ACDB-41	
113	IDC	Incoming Digit Conversion	NFCR-49	
114	AUXS	ACD-D Aux. security	LNK-51	
115	DCP	Directed Call Pickup		
116	PAGT	ACD Priority Agent	ACDA-45	
117	CBC	Call By Call Service selection	PRA-146, IEC-149	
118	CCDR	Calling Line ID	CDR-4, ISDN-145	
119	EMUS	Enhanced Music	MUS-44	
120	PLDN	Group Hunt/DN access to SCL		
121	SCMP	Station Camp on		
122	COMDT	Common DAS/DPNSS DTRK Package		
123	DPNSS	DPNSS		

Table 8: Software Package Dependencies

Pkg #	Mnemonic	Name	Package Dependency	Comments
124	DASS2	DASS2	14	Not supported on Option 11/11E/11C
125	FTC	Flexible Tone and cadences		
126	OPCB	Operator Call Back		
127	BKI	Attn. Break-in		
128	MFC	Multifrequency Compelled Sig.		
129	DTI2	2.0 Mb DTI2		
131	SUPP	International Supp. Features		
132	TABR	Trunk Baring		
133	ENS	Enhanced Night Service		
134	AFNA	Auto. Forward No Answer		
135	MFE	MFE Sig. (France)		
136	JDMI	2.0 Mb Digital MUX interface (Japan)		
137	LSCM	Local Steering Code Modification		
138	DTD	Dial Tone Detector		
139	FFC	Flexible Feature Code	CCOS-81, SS5-73, NCOS-32, CCOS-81, ISDN-145, SS25-18, NCFR-49	

Table 8: Software Package Dependencies

Pkg #	Mnemonic	Name	Package Dependency	Comments
140	DCON	M2250 TCM Console	DSET-88	
141	MPO	Multi Party Operation	FTC-125	
144	ABCD	16-Button DTMF		
145	ISDN	ISDN Sig.	DCP-115, NTWK-148, PRA-146/BRI -216	
146	PRA	Primary Rate Interface	PBXI-75, ISDN-145, DDSP-19	
147	ISL	ISDN Sig. Link	ISDN-145	
148	NTWK	Advanced Network Services	NARS-58 or CDP-59, PRA-146 or ISL-147, NSIG-37	
149	IEC	Inter-exchange Carrier	PRA-146	
150	DNXP	Direct Number Expansion	CDRE-151	
151	CDRE	CDR Expansion	CDR-4, DNXP-150	
153	IAP3P	Application Module Link	CSL-77, IMS-35	
154	PRI2	2.0 Mb PRI		
155	ACNT	ACD Activity Code	AUXS-114	
157	THF	Centrex Switchhook Flash		

Table 8: Software Package Dependencies

Pkg #	Mnemonic	Name	Package Dependency	Comments
158	FGD	Feature Group D	BARS-57, NARS-58 (recommended)	Mutually exclusive with packages 26, 27, and 56
159	NAS	Network Attn. Services	BARS-57, NARS-58, or CDP-59, BQUE-28, NCOS-32, FCBQ-61, ISL-147	
160	FNPN	Flexible Numbering Plan	BARS-57, NARS-58, or CDP-59	
161	ISDNS	ISDN Suppl.	Pkgs 14, 28, 32, 57, 58, 59, 61, 145, 159, 146, 147	
162	SAR	Scheduled Access Restriction	Pkgs 25, 52, 139, 32, and 86	
163	MIN	Message Intercept		Not supported on Option 11/11E/11C
164	LAPW	Limited Access to overlays		
165	RPE2	2.0 Mb RPE2		
166	HOSP	Hospitality Mgmt.		
167	GPRI	1.5/2.0 MB Gateway		
168	TMON	Traffic Monitoring		Not supported on Option 11/11E/11C

Table 8: Software Package Dependencies

Pkg #	Mnemonic	Name	Package Dependency	Comments
169	COOP	Console Operation		
170	ARIE	Meridian Modular Tel	DSET-88 or TEST-89	
171	JTDS	Japan Tone and Digit Service		
172	CPGS	Console Presentation Group Level Services	TENS-86	
173	ECCS	Enhanced CCS	CCOS-81	
174	AAA	Attn. Alternate Answering		
175	NMS	Network Message service	Pkgs. 10, 35,45, 46,77,145,148	
176	DTOT	DID to TIE		
178	EOVF	Enhanced Overflow	TOF-111	
179	HVS	Hosp. Voice services	Pkgs. 7, 10, 17, 35, 40, 45, 46, 77, 109, 103	
180	DKS	Digital Key Sig.	Pkgs. 7,10,17,35,40, 45,46,77,109	
181	SACP	Semi-automatic camp-on		
182	TFM	Trunk Failure Monitor		
183	VNS	Virtual Network Services	Pkgs. 58,32,14,145, 147,148,161	

Table 8: Software Package Dependencies

Pkg #	Mnemonic	Name	Package Dependency	Comments
184	OVPL	Overlap Sig.	FFC-139, MPO-141	
185	EDRG	Executive Distinctive Ringing		
186	POVR	Priority Override		
187	RPA	Radio Paging		
188	L1MF	L1-MFC Signalling		
189	SVCT	Sup. Console Tones		
190	UK	UK H/W support		
191	SECL	Series Call		
192	RVQ	Remote Virtual Queuing		
193	RCK	Ring Change Key		
195	FAXS	HiMail Fax Server Interface	Pkgs. 38,61,75,145, 146/147,148	
196	OHOL	On Hold on Loudspeaker		
197	FTA	French Type Approval		
198	FFCSF	Boss Secretary Filtering		
200	AINS	Auto. Set Based Installation		
202	IPRA	International PRA		
203	XPE	Extended Peripheral Equip.		

Table 8: Software Package Dependencies

Pkg #	Mnemonic	Name	Package Dependency	Comments
204	XCT0	Enhanced Conf., TDS, MFS	XCT1-205	
205	XCT1	Superloop Admin.		
206	MLWU	Multi-Language Wake-up	AWU-102,PM SI-103	
207	NACD	Network ACD	Pkgs. 28,148,178	
208	HSE	Hosp. Screen Enh.	ARIE-170	
209	MLM	Meridian Link Module	IAP3P-153	
210	MAID	Maid Identification	Pkgs. 81,99,100,103,208	
211	MLIO	Multi-Language CPND		
212	VAWU	VIP Auto Wake-up	AWU-102	
214	EAR	Enhanced ACD Routing	ACDB-41	
215	CCR	Customer Controlled Routing	Pkgs. 77, 214, 247	
216	BRI	Basic rate Interface	Pkgs. 203, 222, 235	
218	IVR	Hold in Queue for IVR	CCR-215	
219	MWI	MWI Interworking with DMS		
221	CIST	DTI/3-wire analog trunk		
222	MSDL	Multi-purpose Serial Data Link	Pkgs. 145,146,147,227,228,35,77,153	

Table 8: Software Package Dependencies

Pkg #	Mnemonic	Name	Package Dependency	Comments
223	FC68	FFC Comp		
224	M911	Meridian 911	Pkgs. 19,153,214,24 7,225,209,40, 41,45,4,5,42,4 3,50,51,95,10 7,118	If 50 and 51 are enabled, 42 i not needed
225	CWNT	Call Waiting Notification	DDSP-19, ACDB-41	
227	MSDL SDI	MSDL SDI		
228	STA	Single Terminal Access		Not Supported on Option 11/11E/11C
229	SSAU	Station Specific Authcode	BAUT-25	Not Supported on Option 11/11E/11C
230	MDP	Manufactured Delivered Patches		Not Supported on Option 11/11E/11C
231	DNWK	DPNSS Network Services		
232	PEMD	Pulsed EAM		Not Supported on Option 11/11E/11C
233	BRIT	BRI Trunk Application		
234	CDR-NEW	New Format CDR	CDR-4, CDR-5	
235	BRIL	BRI Line Application	BRI-216, ISDN-145	
236	ARCL	AC15 Timed Recall		

Table 8: Software Package Dependencies

Pkg #	Mnemonic	Name	Package Dependency	Comments
240	MCMO	Meridian Companion	Pkgs. 19, 46, 95, 145, 146, 147	Supported on Option 11C
242	MULI	MultiUser Login		
243	ALMR_FILTER	Alarm Filtering	HIST-55	
245	SML	System Message Look-up		
246	VMB	Voice Mail Box	CPND-95, ALRM_FILTER-243 recommended	
247	CLID	Call ID		Not Supported on Option 11/11E/11C
248	MPH	Meridian 1 Package Handler		
250	DPNA	Direct Private Network Access	Pkgs. 22, 7, 25, 63	
251	SCDR	Station Activity Record	CTY-5	
252	KD3	Spanish KD3 DID/DOD Interface		
253	ARFW	Attn. Remote Call Forward	Pkgs. 139,73,145,58,59	
254	PHTN	Phantom TN Operation	FFC-139	
255	INBD	Intn. nB+D		

Table 8: Software Package Dependencies

Pkg #	Mnemonic	Name	Package Dependency	Comments
256	ADMINSE T	Set Based Admin.	Pkgs. 164, 139,19,88,95, 170,200	Automatic Installation - add pkg. 200 for Option 11 Full ISL & VNS not supported Supported on Option 11C - requires country specific data on SDC plus EDC for storage Not supported on Option 11/11E/11C
258	ATX	Autodial Tandem Transfer	EES-10, THF-157	
259	CDRX	CDR Enhancements		
261	EURO	EURO ISDN		
262	SAMM	Stand-alone Meridian Mail		
263	QSIG	ECMA-QSIG		
264- 280	SMLL	System Message Lookup (Country Specific)		
283	UIGW	ISDN/DPNSS DASS Gateway		
284	DPNSS 1891	DPNSS 1891		
285	CHINA	Attn. Monitor		
286	REM_IPE	Remote IPE		
288	DPNSS ES	DPNSS Enhanced Services		
289	ADSP	ACD Disconnect Supervision		
290	CCB	Collect Call Blocking		
291	NI2	NI-2 TR-1268 PRI basic Call	ISDN-145,PR A-146,MSDL- 222	

Table 8: Software Package Dependencies

Pkg #	Mnemonic	Name	Package Dependency	Comments
292	CHTL	China Toll Loss Plan	Pkg. 164, 243	Pkg. replaced with TATO 312
293	TAT	Trunk Anti Tromboning		
294	BTB	Busy Tone Detection		
296	MAT	Network Access to M1 Maint. function	Pkg. 40,41,42,45,50,51,88,170,116,139,254	Not supported on Option 11/11E/11C
297	MQA	Multiple Queue Assignment		
298	CPIO	Call Processor I/O		
299	CPNET	CPI Processor Network	FFC-139	Not supported on Option 11/11E/11C
301	CPP	Calling Party Privacy		
302	MOSR	Mobility Server		
303	MMO	M1 Microcellular Option	Pkgs. 303, 216, 254, and MAT5 dependencies 164, 242, 296, and optionally 243	Supported on Release 22.37 and later
305	QSIGGF	QSIG GF Transport	QSIG-263,ISDN-145,PRA-14,MSDL-222	

Table 8: Software Package Dependencies

Pkg #	Mnemonic	Name	Package Dependency	Comments
306	CPRKNET	Call Park Networkwide	CPRK-33, NAS-159	
307	PAGENET	Call Page - Networkwide		
309	MASTER	Euro ISDN Master Mode		
310	CPCI	China: Called Party Control on Int. Calls	MCT-107	
312	TATO	Trunk Anti Tromboning	ISDN-145,PR A-146 or ISL-147, MSDL-222; Recommended 148	
313	ISPC	ISDN Semi-Perm Connection -Australia		
314	MMSN	M1 Mobility Multi-Site Networking	Pkgs 302, 303, 145, 146, 147, 148, and 58 or 59	
315	OPEN ALARM	Open Alarms	ALRM_FILT ER-243, MAT-296	
316	QSIG_SS	ISDN Qsig Supp. Services	QSIGGF-305	
321	QTN	Queue to NACD		Supported on Release 22.46 and later
323	EISDN	EISDN Supp. Services		

Table 8: Software Package Dependencies

Pkg #	Mnemonic	Name	Package Dependency	Comments
324	NGEN	New Generation Connectivity		

Packages Introduced in Release 22

The following table provides a list of the packages introduced in Release 22, their mnemonics, and their package numbers.

Table 9: Packages introduced for X11 Release 22.08D

Package Name	Mnemonic	Package Number
Call Page Network Wide	PAGENET	307
Call Park Network Wide	CPRKNET	306
Called Party Control on Internal Calls	CPCI	310
Euro Supplementary Service	ETSI_SS	323
Master Mode	MASTER	309
ISDN QSIG Generic Functional protocol	QSIGGF	305
ISDN Semi-Permanent Connections	ISPC	313
Open Alarms	OPEN ALARM	315
QSIG Supplementary Service	QSIG-SS	316
Trunk Anti-Tromboning	TATO	312

Table 10: Packages Introduced with Release 22.46

Package Name	Mnemonic	Package Number
Mobility Server	MOSR	302
M1 Microcellular Option	MMO	303
M1 Mobility Multi-Site Networking	MMSN	314
Queue to NACD	QTN	321

Packages not supported on Option 11C

The following table lists the packages which are not supported on Option 11 machine types.

Table 11: Packages Not Supported on Option 11

Package Name	Mnemonic	Package Number
Remote Peripheral Equipment 1.5	RPE1.5	15
Centralized Attendant Service (Main)	CASM	26
Centralized Attendant Service (Remote)	CASR	27
Tone Detector	TDET	65
Resident Debug	RESDB	82
Automatic Trunk Maintenance	ATM	84
2 Mb. Digital Mux Interface (Japan)	JDMI	136
2 Mb RPE	RPE2	165
Traffic Monitoring	TMON	168
MSDL - SDI	MSDL SDI	227
Single Terminal Access	STA	228
Manufactured Delivered Patches	MDP	230
Pulsed EAM	PEMD	232
Meridian 1 Packet Handler	MPH	248
Remote IPE	REM_IPE	286
CP1 Processor I/O	CPIO	298
CP1 Processor Network	CPNET	299

Chapter 6 – Resolved Problems

BV37132	CDR records are incorrect when using network auth code from an analog (500) set and the auth code is not re-prompted after the hookswitch flash to make a second call. See the System Enhancements Section.
BV44481	At one site, after upgrading from Release 19.22 to Release 21.05, there were BUG415 and 420 messages being output, but these were not service affecting.
BV44606	At one site, ACD agents are getting busy tone while trying to log in with their assigned Agent ID indicating that the Agent ID is already in use whereas the fact is the Agent ID is not in use.
BV46457	A BRI Trunk ringing call is rebuilt on the originating end if the originating end is system initialized. After initialization, the call is restored and hears ringback, but when answered, the call is dropped.
BV49867	Incorrect disconnect sequence on QSIG-EUROISDN interface.
BV49869	“Ovl111 044 aud” printed although overlay 44 is not in the background.
BV50016	Call Detail Recording (CDR N) from remote node passing through tandem, shows dialled digits for an earlier call made from the tandem node. Only a problem with PRI2. Works with ISL.
BV50708	Call processing not tandem on MCDN to MCDN transit.
BV50824	Number of calls dropped during traffic testing exceeds specification. Failures are related to one way speech path.

BV51019	Intermittently, the switch stops normal call processing and call timers speed up.
BV51168	Pretranslation on Paging call generates BUG4005.
BV51472	When a single route is configured with multiple members as PUL or LVL RAN machine types, calls are not queued correctly e.g. each call should be indexed up to the next free TN/Route combination, and hear the appropriate RAN message, or given the correct call processing treatment, e.g. ringback when that RAN machine is busy.
BV51634	The TFC002 report does not peg all trunks busy (ATB) on incoming ISA service routes.
BV51709	No speechpath if a 500 set dials out to EURO ISDN Central Office.
BV51792	Loadware development is required for supporting the ELF packet (NT1P63CA). The loadware is changed to support both the EOI and ELF packets.
BV52217	At one site, an ISDN ISA INWATS call using IDC to a set that is in lockout state forwards to the NIT1 DN when the attendant console is in NIGHT mode instead of the external party receiving busy tone.
BV52929	When both Q-Sig Supplementary Services Call Completion on Busy (CCBS) and Q-Sig Name Display Services (QNDS), the name display for both sides are not displayed correctly.
BV52946	The CDR "N" (normal) record is missing the charges (PPM) when a VNS call is transferred by the attendant.
BV52947	The CDR "E" (end) record is missing the charges (PPM) when a VNS call is blind transferred by the attendant and the Release 22 Trunk to Trunk Connection feature is configured.
BV52972	Some sets with privacy (MCRA class of service) are locking up intermittently.
BV53328	At some sites, BUG105 messages are being output when DTI trunks are used.

BV53982	Removing the Multipurpose Serial Data Link board without disabling it first in the software and then re-insert the board immediately results in a system cold start.
BV54031	The midnight routines took a long time to complete at one site.
BV54400	Option 71 with Octel has Network Message Service (NMS) to an Option 11. If the Message Waiting Light is on and the set has a service change done, when the user retrieves their message, the lamp stays on. The lamp can be cancelled with a MCK key but when the next message is left, the lamp does not come on.
BV54413	The Departmental Listed Directory Number package is equipped, and is being used with auto terminating COT trunks to the LDNs. Each LDN is associated with an attendant console. The ICI key will flash for an incoming call and the attendant cannot access the ICI to answer the incoming call. When BUG250 message is printed out, usually 3 - 4 minutes later, the console is freed up to accept other calls.
BV54637	When doing a data dump an "INVALID BLOCK LENGTH" appears after "ARIES". This problem only occurs when you build a new system with M2616 sets.
BV54654	When an existing DN is used as an entry for MUD_DN prompt in LD15, system will output SCH1328 (invalid input). SCH1328 has been replaced with SCH242 (directory number conflicts with existing DN) to provide more information to user.
BV54756	Some CDR records are truncated when they are larger than 128 characters and the baud rate is slow (300).
BV54770	ISDN PRI channels are going into MBSY state when the active call on the channel is released.
BV54771	On option 11C, PRI call-in-progress on 1.5meg & DCHI pack did not survive initialization. The DCHI pack had just been replaced with an MSDL card.
BV55058	BRI datacall not possible over DT12 ISL.

BV55828	An incoming NI2 call to a set that is CFW all calls to Meridian Mail has an extra progress indicator in the connect message. Both progress indicators of 8 and 2 are present in the connect message. Only progress indicator 2 should be in the connect message.
BV55928	Calls are NACD with VNS. The source queue has the target queue with a 0 second timer. An ACD call comes into the source queue. The call should get RAN/Music treatment until the alert message is received back on the VNS D-channel. Instead no RAN or Music treatment is given, the call takes 8 - 12 seconds to setup, silence is heard until the alert message is sent from the target switch. Note that this problem only occurs when the originating trunk has DTN class of service.
BV56155	An incoming ISA DID call to a vacant number does not get routed to the console group as defined in LD 93.
BV56289	When ESN/NARS is configured incorrectly, the system can sysload or initialize (INI0005).
BV56478	When configuring a portable set and key 0 is not configured, if a SCR key is not entered when the portable is first built then the server supplies a incorrect DN. To resolve this problem, SCH0196 (A key 0 DN key is required on a Mobility set) will be presented to user and user will be reprompted for the SCR key.
BV56540	With NAS activated, an ST system on Release 14 cannot tandem calls to other switches.
BV56623	In some cases, there is wrong information on the display of the originator of a call which is forwarded, in the standalone case as well as networkwide on MCDN with RCAP ND3.
BV56718	Disabling a TTY in AX mode causes it to not function.
BV56812	On systems using distant steering codes and local steering codes between two nodes, visiting portables cannot make or receive calls if the variable length DN is different at the two nodes (e.g. site A uses 4 digits and site B uses 5 digits).
BV56879	Orion: leading 0 is missing in caller list (euro-isdn).

BV56990	When upgrading to Release 22 with System Access Enhancements, the passwords are encrypted with the login names. If the user uses a TTY to login, the passwords do not match. This problem does not occur with a STA terminal.
BV56992	The Clock Controller cannot synchronize to a default frequency during a cold power start, since there is nothing for the clock controller hardware to track on.
BV57032	For systems with MAT 5.30.5 and later, the short trap 6.5 is not being sent to open managers.
BV57034	When the call join feature of MPO is used, the set which originally called the set doing call join has its DN key inoperable and incoming calls receive busy tone. To clear the problem the DN key is pressed, but BUG115 message is output. When a conference call is joined to an existing call either a BUG4231 message is produced for a M2616 set or BUG4231 message and BUG5182 message is produced for a M2317 set. This problem is not service affecting.
BV57093	Incoming DPNSS CFNA over MCDN from BRI which rings continuously.
BV57238	When the Multi-Party Operations Package is enabled, sometimes there are system initializations or bus errors which may occur.
BV57321	Phantom 2317 sets appear after service change.
BV57353	If remote call forward on node X is forwarded to an invalid DN over VNS to node Y and Node Y has VNR(vacant number routing) programmed, BUG6013 (RCFW message response timeout. For Attendant RCFW operation, the remote node requires Attendant Network Remote Call Forward package 253.) is printed, causing the facility message to loop around on the VNS D-channel and the remote node to be blocked.
BV57499	When using the M2616 set, the handsfree redial does not work, the volume control is inoperable, and there is some delay in the speechpath after answering on an ACD set or SCR call.
BV57542	When a call is transferred to Meridian Mail by using the express messaging and dialing the express messaging access code followed by an autodial key which has the DN of another set and the transfer is completed, double timeslot noise occurs.

BV57555	The Busy Lamp Field Array on the M2250 Attendant Console does not have the DN marked busy on it. Instead the empty array is displayed on the BLF screen.
BV57630	Upgrade menu output overwrites itself on the Option 11C.
BV57653	A call is presented to an idle ACD agent with call force enabled, FCFT > 0 and ISAP = YES. If the caller disconnects when the agent is still in the FCFT queue, no call abandoned (CAB) message is sent to MAX. This call is also not pegged in the ACD-C reports.
BV57717	When calls are tandemed from a non Meridian 1 switch over the ISDN T1 Q-Sig GF interface so that the LOC code is used on one Meridian 1 to reach another Meridian 1, the incoming call is rejected from the first Meridian 1.
BV57718	The calling user sees his/her name displayed for a gateway call originated from a Meridian 1 and going to a non Meridian 1 switch through another Meridian 1.
BV57797	BTNR 190 states that calls with a Service Indicator Code of Telephony(00), should not have the OLI string. The Meridian 1 however includes the OLI string for Telephony calls. The M1 cannot generate a SIC of telephony, however if one is received then it is passed on by DASS. This problem has recently been highlighted because OLI/CLI transmission over the public network has recently been enhanced. OLI is now transmitted to private subscribers.
BV57830	When using call trace with release 22.07 from maintenance windows with MAT 5, the system will sysload. This problem does not occur on releases 22.06 or earlier since the stack size on the switch was adequate.
BV57852	BUG105 due to TS Network Memory check on Opt 11.
BV57886	BUG5374 is printed after a 500 set is moved from one TN to another, and then it is included in a AO6 conference call with: 3 - 500 sets, 2 - 2616 sets.
BV57887	At one site, an ISA call to a set with Call Forward All Calls, fails to complete due to the Meridian 1 sending the wrong (unsupported) progress indicator.
BV57944	Individual channel restart cannot be completed successfully on ETSI QSIG GF (ESGF) interface. Restart acknowledge message does not contain Restart Indicator IE. The B-channel on the side initiating the restart is left in lockout.

BV58054	The Meridian 1 Channel ID format is different from a non Meridian 1 switch when a backup D channel is used and the channel ID is implicitly defined (TR1268 NI2 Channel ID format 5ESS). Incoming calls do not complete when the backup channel is active and the incoming call is received on a channel that is on the backup span.
BV58055	When using Overlay 16 to build NI2 trunks as ISA, service change allows the input of NI2 trunks. ISA is not currently supported on NI2 trunks.
BV58119	The clock controller cannot be enabled after power down/power up of the system. System needs to be initialized for the clock controller to be enabled.
BV58322	There are two transfer call ids in the USM message when a call transfer is completed.
BV58368	Since upgrading to Release 21.35, a setup message is sent out immediately after the Autodial key is depressed when the called number is equal to the SPN (special number to be screened) in the setup message. This does not allow the user to manually dial digits to complete the call. It appears that the End of Dial timer is not used when a SPN is included in the Autodial key. This problem does not occur when dialing manually.
BV58394	Two portable sets are calling each other simultaneously and double timeslot noise was received instead of busy tone.
BV58397	Incoming call to ISDN with CLID information drops the call.
BV58428	On a Meridian-1 connected to the Central Office with DTI2 DC5D signalling, an idle signal does not take the DTI2 trunk out of lockout state
BV58477	When using MAT 5 on Ethernet, the throughput is much slower compared to when doing service change on the TTYs without MAT 5.
BV58483	If a hotline key is used to call Meridian Mail, the prime DN is sent in the PCI message instead of the DN assigned to the hotline DN.
BV58512	During an established call on a portable, the portable presses send to transfer the call to another DN, and if the other DN is busy, the caller hears busy tone and the call must press send to transfer 6 to 8 times to return to the first caller.

BV58546	Multiple sysloads with IOD318 and BUG5546 messages.
BV58548	The call offered message is coming before the progress ringing message. This causes problems with the screen pops.
BV58552	Cannot configure any trunk for PRI2 BRI trunk route.
BV58564	If the originating DN is a 2-way hotline key, the calling party DN sent to Meridian Link is 0 bytes in length.
BV58646	Unable to retrieve call from hold on a different set.
BV58652	Portable sets were not set up to handle an inband tone for call waiting tone on key other than call waiting key, therefore portable users are only aware of the first call that is waiting for them.
BV58893	Continuous INI2000 with 2616 set using Set Relocation.
BV58904	When the secondary DN makes a call transfer or conference, the Status Change Message THIS PARTY DN IE FIELD contains the primary DN value instead of the secondary DN value.
BV58966	QSIG GF doesn't tandem properly Facility message
BV58990	When converting from release 21.43 to release 22.08, conversion fails with a SYS3047 (Automatic conversion is not available for a given data base. Data base on tape is not updated to minimum release.) message.
BV59026	Meridian LINK does not receive CLID on tandem calls.
BV59027	In LD 14, it is not possible to set SIGL = EAM for a DID trunk, if package 190 (UK package) is restricted.
BV59078	Conference fails on attendant extended calls.
BV59117	See description for BV57499
BV59150	BUG115, BUG5244, AUD028. EUROISDN. Channel restart on wrong channel.

BV59178	Overlay 51 ICP update does not execute update command correctly.
BV59179	See description for BV57499
BV59212	When a wireline answers a call from another wireline, a twinned portable also answers the call and then disconnects, a BUG6505 (Cref returned by MOB_GET_CREF is invalid) is given. There is no impact to system or call.
BV59239	See description for BV57499
BV59243	A defective radio continues to direct calls to it, which effects the system performance.
BV59342	The TEIs are not being cleared immediately when the terminals were unplugged. The number of TEIs should be decremented within a few seconds after the terminal is unplugged.
BV59385	Wrong Speed Call List index (and AUD014) when using Pilot DN (PLDN) Flexible Feature Code (FFC).
BV59406	STAT in LD 54 shows MFC units idle, but STAT in LD 32 shows MFC units MBSY. This problem occurs when the midnight routines are run, the MFC units are put into MBSY and AUD587 message is printed out. This problem is not service affecting.
BV59407	A M2317 set makes a call using an analog ISL trunk to another M2317 set. LD 80 is used to trace the call and BUG5861 is printed. This problem is not service affecting.
BV59465	The background terminal outputs multiple'EQUP FAIL' messages and the automatic wake-up calls revert back to the operator. This problem only occurs if RANF is configured in a different group from the sets.
BV59548	SCH4599 message is printed when defining auth codes for new 500/2500 DNs when package 229 is equipped (Station Specific Authorization Codes). As a work around, the user must step through the programming to the end, when memory is updated and the user goes back and executes a change when the auth code entries are accepted.

BV59564	When converting to release 22, when sets are configured with keys that utilize the full allocated memory (256 words) the sets get removed from the database.
BV59626	BRI calls fail due to T304 timer timeout on APAC AUST.
BV59680	Opt11c C-drive fills up resulting in no sysload.
BV59742	On a customer with at least 2 attendants with the RTSA prompt set to RSAX, not all calls made by an attendant return to the attendant after the timeout.
BV59784	The progress message from a hold request on an analog set (500/2500) has the wrong CALLER ID IE.
BV59937	Agents without ACD-D package are not able to configure the ACNT key. SCH3621 message is output.
BV59998	BARS will not work with an FCAS (Free Calling Area Screening) when using DISA with DTL. This problem does not occur with analog trunks.
BV60022	An invalid call register in the CCR priority queue for a given CDN on a system with the IVR package configured has produced system initializations when the CCR script has attempted to access the invalid call register.
BV60048	On an ISA DID route when programmed with RCLS (route class marked as internal) = INT, the call is forwarded no answer to the EFD (Flexible Call Forward No Answer DN for external calls) instead of the FDN (Flexible CFNA DN). This problem does not occur for analog DID routes.
BV60137	When a call fails to use a VNS D-channel and goes on onto UIPE trunk only, BUG5180 and ERR5429 messages can be seen.
BV60209	Bus errors occur when the originator of an internal three party call disconnects. This problem only occurs if one of the two remaining parties is an analog (500/2500) set with call forward and speed call configured.
BV60266	All the problems we will discuss are about the handling of congestion by UIPE. At the call establishment, when the call is rejected with a cause of congestion or no channel available, we get BUG messages (a first BUG115, then 4244, 35, 4005, 115 again) when the UIPE trunk is used by VNS into an NACD network.

BV60357	System/Security ID printing all zero's.
BV60358	A TR1268 NI2 RESTART REJ is sent to a 5ESS NI-2 in backup DCH environment. A RESTART ACK message should be sent instead, since the 5ESS is attempting to restart on channel 1 on the backup DCH channel.
BV60455	BRIL not released if incoming call comes in from a 500 set.
BV60598	Run CCR with a script for CDN 2229 to give ringback, queue to 2200, queue to 2999. Create a night table for 2999 so that it call forwards to customer 3. Have all agents busy except for ACD DN 3200. Establish a call between two sets for the same customer. Conference in a customer 3 NACD agent by dialing the CDN 2229. Answer the call at ACD DN 3200. Disconnect the first set. Disconnect the second set. BUG681 message is printed out.
BV60627	500 set cannot dial international number: In sweden after the international prefix and country code, the Central Office provides dialtone (that means on EURO that a progress #8 is received from the CO). After that it is not possible to complete the dialling.
BV60643	GPHT/PLDN/ACD BUG681/INI000 0000000C messages may occur when MQUE=ALL.
BV60648	At one site, calls are presented to an ACD agent even though the set is in not ready state. The agent had to first put an ISDN or ACD call on hold and keep the handset onhook. If the call is released while the set is still onhook, the NRD lamp starts flashing. After this the problem occurs.
BV60681	Incoming call to ISDN with CLID-R information drops the call.
BV60733	After upgrading to Release 22.08 or installing new systems with package 243 (Alarm Filtering) and 296 (MAT) on, some systems will not print maintenance messages. If the site turns package 243 and 295 off the problem no longer occurs.
BV60887	When a QTN (Queue to NACD) call is abandoned, a NOVF message is sent. This NOVF message is in HSL Protocol 10 format (len = 10) instead of HSL Protocol 11 format (len = 14). Also applies to when a QTN call is answered locally. Requires the NACD (Option 178), Queue to NACD (Option 321) and CCR (Option 215) packages.

BV60891	When a QTN (Queue to NACD) call is abandoned, there is no ICAB or ICCN HSL messages. Requires the NACD (Option 178), Queue to NACD (Option 321) and CCR (Option 215) packages.
BV60934	When a QTN (Queue to NACD) call is dequeued from the Routing DN, the ICCN message does not have QTN_flag = 1, instead of 0. Requires the NACD (Option 178), Queue to NACD packages (Option 321) and CCR (Option 215) packages.
BV60936	When a QTN (Queue to NACD) call is dequeued, a NOVF-off HSL message is received but it has the abd_at_src = 1 instead of 0. Requires the NACD (Option 178), Queue to NACD packages (Option 321) and CCR (Option 215) packages.
BV60943	SCH2017 messages are generated continuously after defaulting (carriage return) past the DRNG prompt while programming a new PRI ISA service route in LD 16.
BV60945	When a QTN (Queue to NACD) call is answered, the RCAA received has the QTN_flag in the wrong bit position, at bit 2 instead of bit 3. Requires the NACD (Option 178), Queue to NACD packages (Option 321) and CCR (Option 215) packages.
BV61122	During clear-down of a Multipurpose Serial Data Link (MSDL)/universal Integrated Services Digital Network protocol call, the release message is occasionally missing. This problem results in the channel being locked out on the MSDL. However, the channel appears to be idle if viewed using overlay 60.
BV61128	DPNSS to attendant, if attendant extends calls over DASS/DPNSS, the attendant can't get back to talk to SRC without pressing RLS-DEST.
BV61253	Software upgrade fails to complete on an Option 11C.
BV61385	With multi-user login allowed, Overlay 86 and Overlay 87 can both be loaded, any changes made in either while other overlay is loaded causes corruption of the ESN block.
BV61473	See description for BV60887
BV61501	For a VNS call with UIPE followed by another VNS call, when the originator goes on hook at reception of ring back tone, a BUG5180 message is printed out.

BV61592	When a QTN (Queue to NACD) call is presented to the remote agent, the ICAB HSL message is missing the DNIS info. This only occurs when a QTN call is presented to the remote agent. The DNIS information is there when all agents are busy. Requires the NACD (Option 178), Queue to NACD packages (Option 321) and CCR (Option 215) packages.
BV61632	Multiple BUG5416 with invalid TN's.
BV61635	There are no second and third USM ringing messages for call forward no answer, second level call forward being sent to Meridian Link.
BV61663	Mobility: Portable cannot make any outgoing calls.
BV61780	Sites that have more than one TEI's per Digital Subscriber Loop and upgrades to 22.15 the BRSC cards may not function. All equipped MISP cards are functional.
BV61832	Abort option on Option 11C SW install program deletes menu items.
BV61881	Private lines are not working correctly on EPE when calls are via the CO to an analog Loop Start private line.
BV62035	When an EXUTJ card is plugged into a system without Busy Tone capabilities, an ERR5333 is printed when a Busy Tone Disconnect signal is received from the Central Office.
BV62131	Cannot enable the BRIL application on the MISP in LD 32. A BRI824 message is printed with "The MISP failed to get enabled".
BV62139	A call which has time overflowed to the target ACD-DN is not presented to the MQA (Multiple Queue Assignment) agent. Also a CDN (Control DN) call, queued to an ACD-DN is not presented to the MQA agent.
BV62159	While configuring the BRIE application in LD 27, SCH101 message is output.
BV62345	Many RCV001 messages are being output causing the midnight routines to initialize. This problem was caused by an interaction with Network Message Center and Call Sender.

BV62347	When making a data call from a M2616 set, the call is blocked, and both cpu's lockup. This only occurs when you hit the "program" and "*" keys to release the data call, the switch will lockup with "VECTOR 4D UNIMPLEMENTED" on the CP display.
BV62393	In LD 20, you are unable to print a music trunk when the Mobility packages are restricted (Options 302 and 303).
BV62435	There is loss of service to loops running off of fibre-remote multi-IPE and many ERR020's.
BV62476	After upgrading to Release 22, there are SYS9999 and SYS4416 messages printed out for Mobility which are reserved for Meridian 1 not Mobility.
BV62488	Mobility cannot change the DN on a portable with Multi-site. The Multi-site database was not updated when a portable was service changed.
BV62497	When making a call from a portable and hanging up, the DN continues to ring until another call is made to another DN from the portable.
BV62498	If a busy portable set that is configured with call waiting allowed in LD15 hears the call waiting tone and disconnects then BUG0115 (Terminal does not match DN or TN in call register) is generated.
BV62573	DTC0007 output continuously after upgrade to 22.16.
BV62627	When upgrading a system and configuring EICM and MXC, occasionally can not reuse the same card address. If there is a problem with reusing the same card address, user will receive a message that the "Card address - Invalid value: Unconfigured hardware".
BV62678	UIPE-VNS call with congestion on the VNS bearer. BUG4023 output at the time of disconnecting the UIPE call.
BV62871	Non call-related SETUP causes an initialization at QSIG GF-MCDN gw
BV62877	Intermittently the system generates SCH6755 when adding a new DN on a key to a M 2616 set. (LD 11)

BV63037	Incorrectly idled call registers result in BUG4001s (Call Register idled when SON CR still linked) during midnight routines.
BV63057	The EIMC is causing a memory leak which in turn is causing Mobility to have no available memory.
BV63059	The Mobility Traffic in LD 2 for the Operational Measurements is incorrect.
BV63065	When LD 17 was run with “PBXH” set, NPR messages were sent for phantom loops causing the system to have an INI-2F. This is because phantom loops have no physical hardware, but NPR messages were still being sent to the hardware.
BV63066	Customers will hear the Recorded Announcement (RAN) then receive fast busy on sites using a VPS card to give the RAN for the ACD queue and that have the ASUP prompt for the RAN route set to NO.
BV63173	When placing a call using AC1+NSCL+ entry, there is a delay prior to receiving request for auth code. If the user enters additional digits or a pound sign, the dial tone is returned immediately.
BV63181	The protocol version on the neighbor list for an internal cell has version 2 instead of 4. The portable does not work correctly when entering an internal IS-135 RevA cell.
BV63182	Upon initiating a PPP (point-to-point) session from a MAT PC to an Option 81C, the Option 81C’s name is changed to “LOCAL_PPP_IF”. Even after the PPP session is terminated, the host name remains the same with “LOCAL_PPP_IF”.
BV63350	See description for BV62345.
BV63535	After upgrading to 22.08, digital sets can not use Make Call in Meridian Link to initiate a call from an idle digital set to another digital set.
BV63565	Console operator extends a call to a user, the call recalls to attendant who tries to extend the call again and periodically the console will lock-up. This problem is random and site unique.
BV63744	Mobility load 22.21F will not load on an Option 11C.

BV63859	Occasionally, on sites running 22.15 software, portable sets lock up when involved in three way call with two portable sets and a wireline phone.
BV63918	Site has Backup D-channel to DMS250. The backup D-channel is active and primary D-channel is in standby state. A failure on the span carrying the backup D-channel while there is active calls on the B-channels results in backup D-channel being placed in MBSY state. The primary D-channel does correctly take over in this scenario. This problem only happened with DMS PRI backup.
BV63935	Mobility Alarm severities not identified, set to "info".
BV63957	When deleting a cell that has a hand-off path pointing to it, get a CTS bus-error.
BV64069	The watch dog time out for OA&M was set too low which resulted in a restart of OA&M task when debug messages were turned on.
BV64138	When "INVS 11" is used for operational measurements (in overlay 2), the embedded intelligent mobility processor pack (EIMC) information prints out four times per call. Only the first printout has accurate data.
BV64349	On systems with or without the Mobility packages equipped, a Mobility debug message is shown during sysload process. This problem is not service effecting.
BV64744	No control dialtone after hook flash.
BV64757	Many BUGs, and some call cutoffs, related to VNS over EuroISDN.
BV65275	After locking and unlocking the embedded intelligent mobility processor pack (EIMC) or microcellular transcoder card (MXC) everything seems all right, but calls can not be originated or terminated to or from a portable set. The radio window shows busy-idle state and CTS proclaims "DIGITAL CONTROL LINK SUCCESS". The traffic control radio is still in the "TCC" mode even after all phone calls have ended.
BV65279	A single call Multiple appearance set up between two sets will have only one call per DN. When a wireline set goes offhook and then the user makes a call using the portable with the same DN, the call register is different than if the wireline is onhook resulting in BUG1333 (Terminal activating Individual-hold is invalid) or BUG0115 (Terminal does not match DN or TN in call register).

BV65428	On systems using a CP2 board with at least 32MB DRAM, after the first warm-start the system may lose 4M of heap space during next warm-start.
BV65747	Portable lockup: when MXC freezes, due to radio failure, due to lack of VCH RF frequencies, and on disabled portable.
BV65785	VNS DN's locked up on tandem VNS calls. Cleared by audit.
BV65810	BERR705, BERR115 occur during Lamp Audit of 2317 set.
BV65880	When a new or existing system is loaded with the Aries package for the first time, the Sidetone Objective Loudness Rating (SOLR) prompt under Meridian Modular Telephone Transmission Parameter (ATRN) in LD17 is not initialized/defaulted properly. Sites will have to manually set SOLR to the default value.
BV66127	On an Automatic Number Identification (ANI) call, the originator's dialed digits are displayed on the terminating set's display. This problem is applicable to all machine types using ANI with the Microcellular package turned on.
BV66319	Occasionally the Multipurpose ISDN Signaling Processor (MISP) is not enabled during system initialization.
BV66356	After configuring the mobility portable set in station admin when you try to sync the information over to the M1 MAT is not transmitting any information for the "DES" prompt.
BV66453	Portable set has message waiting allowed. Portable set is on a call when another call comes in on call waiting after second call stops ringing, portable user presses SND twice. Portable set cannot access either call at this point. If the SND is pressed two more times and the original call is ended, the MSP is suspended resulting in portable sets not being able to make or receive calls.
BV66501	Xmodem data transfer on Option 11C can not recover from the introduction of an additional byte (noise)
BV66643	Some BUG information is output to the TTY in garbled format.
BV66647	On release 22.33 and above, ACD agents using 2216 NT2K18xxxx sets will not receive a buzz before call is connected using the call force feature.

BV66731	MISP card on an Option 11 is unstable causing the link to go down and come up quite frequently.
BV66885	Watchdog timeout may occur during initialization on systems equipped with the generic functional protocol (GF) package.
BV66888	BERR705 Bus Error occurring during Task "tSL1"
BV66941	SYTP becomes blank in LD20 when I input BTS JCO/JDID in SYTP in LD 14.
BV67018	INIT during a call forward on no answer back over VNS with euroISDN PRI or R2MFC DTI2 bearer using trunk optimization.
BV67483	SYS0202 messages generated and M3000 sets removed when upgrading from 22.15 (22B) or later software to 22.33 (22C) or later. The workaround is to remove the M3000 sets prior to upgrading to 22C.SYS0202 - Station type does not match card type.
BV67504	On systems running X11 Release 22.35 with Network Customer Controlled Routing (CCR) configured, a user receiving interruptible Interactive Voice Response (IVR) may get one-way speech path when the remote agent becomes available. Site may also get BERR705 messages when the CCR script utilizes a 'Queue to' network followed by a 'Queue to' local directory number. A BUG0105 may occur if the site has virtual network services interworking with Network CCR.BUG0105 - Double timeslot problem prevented.
BV68159	After activating ring again a BUG4005 message is printed when set is notified that ring again was activated.BUG4005 - Lost time slot idle call register.
BV68189	Dial Intercom misoperation may occur if an exception error occurs after sysload with DIG keys configured on digital sets.
BV68571	The total number of messages in the HWI category is incorrect in the RPT database.
BV68707	MSDL;TMMIH Print All History causes BERR705 followed by a cold start.
BV68946	After making ISDN QSIG GF call with Name Display configured, system memory is not correctly released for reuse.

BV69493	Continuous INIs during initialization
BV70048	Option 11C memory leak during data dump
BV70475	PatchMidnight causes stack overflow

References

Table 12: Reference Documentation

Package Name	Mnemonic
Option 11C Documentation	General Information and Planning Handbook (553-3021-200) Software Installation Program Guide (553-3021-310) Upgrade Procedures (553-3021-250) Central Answering Position Guide (553-3011-320) Customer Configuration Backup and Restore Guide (553-3011-330) Fault Clearing Guide (553-3011-500) Installation Guide (553-3021-210) Technical Reference Guide (553-3011-100)
X11 Software Guides	X11 Administration Input/Output Guide (553-3001-311) X11 System Message Guide (553-3001-411) X11 Maintenance Input/Output Guide (553-3001-511)
2216 ACD Set Voice Parameters	Input/Output Guide (553-3001-400) Automatic Call Distribution Features Description (553-2671-110) Commands and Reports (553-2671-112) X11 Features and Services (553-3001-305) Meridian Modular Telephone/Standard Telephone User Guide M2216 ACD Telephone User Guide

Table 12: Reference Documentation

Package Name	Mnemonic
Alarm Management	Input/Output Guide (553-3001-400) System Management Overview (553-3001-300) System Management Applications (553-3001-301) System Management Security (553-3001-302) X11 Features and Services (553-3001-305)
Call Page Network-wide	Input/Output Guide(553-3001-400) ISDN PRI Description (553-2901-100) ISDN PRI Maintenance (553-2901-500) Meridian 1 Telephones (553-3001-108) Meridian Modular Telephone/Standard Telephone User Guide M1250/2250 Attendant Console User Guide
Call Park Network-wide	Input/Output Guide (553-3001-400) ISDN PRI Description (553-2901-100) ISDN PRI Maintenance (553-2901-500) Meridian 1 Telephones (553-3001-108) Meridian Modular Telephone/Standard Telephone User Guide M1250/2250 Attendant Console User
Call Redirection by Time of Day	Input/Output Guide(553-3001-400) X11 Features and Services(553-3001-305)
CDR 100 Hour Call	Input/Output Guide(553-3001-400) X11 Features and Services(553-3001-305) Call Detail Recording (553-2631-100)
CFW, Break In and Hunt Int/Ext Network-wide	Input/Output Guide (553-3001-400) ISDN PRI Description (553-2901-100) ISDN PRI Maintenance (553-2901-500) Meridian 1 Telephones (553-3001-108)
Automatic Wake-Up	Input/Output Guide(553-3001-400) X11 Features and Services(553-3001-305)

Table 12: Reference Documentation

Package Name	Mnemonic
Call Forward Destination Deactivation	Input/Output Guide (553-3001-400) X11 Features and Services(553-3001-305)
Call Party Control on Internal Calls	Input/Output Guide(553-3001-400) X11 Features and Services(553-3001-305)
Speed Call Delimiter	Input/Output Guide(553-3001-400) X11 Features and Services(553-3001-305)
E.164/ ESN Numbering Plan Expansion	Input/Output Guide(553-3001-400) ISDN PRI Description (553-2901-100) ISDN PRI Maintenance (553-2901-500)
Fiber Remote IPE Phase II	Input/Output Guide (553-3001-400)
Flexible Voice/Data TN	Input/Output Guide (553-3001-400) X11 Features and Services(553-3001-305)
Init ACD Queue Call Restore	X11 Features and Services(553-3001-305) Meridian 1 Telephones (553-3001-108) Automatic Call Distribution Features Description(553-2671-110) Commands and Reports (553-2671-112) Meridian Modular Telephone/Standard Telephone User Guide M2216 ACD Telephone User Guide
ISDN Q-Sig Basic Call	Input/Output Guide(553-3001-400) ISDN PRI Description (553-2901-100) ISDN PRI Maintenance (553-2901-500)
ISDN Q-Sig GF Transport	Input/Output Guide(553-3001-400) ISDN PRI Description (553-2901-100) ISDN PRI Maintenance (553-2901-500)

Table 12: Reference Documentation

Package Name	Mnemonic
Meridian Link Release 5 Enhancements	Input/Output Guide (553-3001-400)
Meridian Mail Trunk Access Restrictions	X11 Features and Services(553-3001-305)
System Access Enhancements	Input/Output Guide (553-3001-400) System Management Overview (553-3001-300) System Management Applications (553-3001-301) System Management Security (553-3001-302)
System Management Features	Input/Output Guide (553-3001-400) System Management Overview (553-3001-300) System Management Applications (553-3001-301) System Management Security (553-3001-302)
Trunk-to-Trunk Connections	Input/Output Guide (553-3001-400) ISDN PRI Description (553-2901-100) ISDN PRI Maintenance (553-2901-500) X11 Features and Services(553-3001-305)
VNS / VDN Expansion	Input/Output Guide (553-3001-400) ISDN PRI Description (553-2901-100) ISDN PRI Maintenance (553-2901-500)
Display of Calling Party Denied	Input/Output Guide (553-3001-400) ISDN PRI Description (553-2901-100) ISDN PRI Maintenance (553-2901-500)
Trunk Anti-Tromboning	Input/Output Guide (553-3001-400) ISDN PRI Description (553-2901-100) ISDN PRI Maintenance (553-2901-500) X11 Features and Services(553-3001-305)

Table 12: Reference Documentation

Package Name	Mnemonic
Meridian Mail Password Suppression	X11 Features and Services(553-3001-305)
68040 Call Processor for Options 51C/61C	Upgrade Overview (553-3001-101) Upgrade Engineering (553-3001-150) Spares Planning (553-3001-153) Equipment Identification (553-3001-154) Product Compatibility (553-3001-156) System Installation Procedures (553-3001-210) Upgrade system installation to X11 R22 (553-3001-258) Hardware Replacement (553-3001-520)

Appendix 1— Option 11C Product Overview

Introduction

This Chapter provides a brief overview of the Meridian 1 Option 11C. It describes the system highlights, the required software, the hardware components which make up the system, upgrade scenarios, and auxiliary product compatibilities.

Overview

The Meridian 1 incorporates many enhancements to the existing Option 11/11E product. The Option 11C is now the PBX system of choice in the 30-400 line size market, offering customers the power of a much larger system in a small package. The Option 11C can address the needs of a small single-site business establishments and that of a larger organization supporting multiple locations in a network.

Technical improvements to the product include a dramatic increase (>7 times over Option 11E) in the real time processing power. Increased real time is delivered through the use of a Motorola M68040 processor on the CPU board. The number of conference loops has been increased giving the Option 11C the capability of having up to 64 conferees (based upon system configuration). Currently the Option 11E offers fiber connectivity between the main and expansion cabinets up to a maximum length of 10 meters. Option 11C provides an additional option to extend remote fiber connectivity up to 3 km away from the main cabinet.

The software for all new system installations and systems converting from Option 11/11E to Option 11C will be delivered via a FLASH software daughterboard. The software daughterboard is installed on the CPU board and remains with the system permanently. The software daughterboard contains all components associated with a particular release of software including software patches, pre-configured customer data, feature sets and other pertinent databases and software.

The software upgrades to the existing Option 11C systems will be delivered via a 40 Mb PCMCIA card. Once the installation or modification is completed successfully, the PCMCIA card can be reused at other sites.

Installation of software, feature sets and ISM parameters is protected by a security keycode scheme. The installation is not allowed unless the correct keycodes are entered. Keycodes are required for all new installations as well as existing system upgrades. They are provided on a keycode datasheet supplied with the software and security device.

Systems wishing to upgrade from a two cabinet copper Option 11/11E to a two cabinet Option 11C have the opportunity to go to a two cabinet fiber interface or retain the copper interface. The copper interface is provided with the introduction of a backward compatible daughterboard.

System Highlights

The Meridian 1 Option 11C enhancements include:

- Commercially based CPU (M68040) providing significant increase in Real Time and memory capacity.
 - The CPU will operate under Wind Rivers Systems VxWorks real time operating system which is the same as the Meridian 1 Option 51C, 61C, and 81.
 - Ethernet Connectivity operating at 10Mbits.
 - Tone service units on the CPU card provides the same tone functions as the following packs: TDS/DTR (NTAK03), XTD (NT5K48), MFR (NTAG26), and XMFC (NT5K21). The CPU card can co-exist with these existing packs, thus allowing customers to continue use these packs on an Option 11C system. Tone services units can now be configured as either 16 DRT/XTD units or 4 units of MFC/MFE/MFK5/MFK6/MFR plus 8 DTR/XTD units.
-

- Increased conference capacity for the system (additional 1 loop allowing 16 more conferees); 1 cabinet - 32 conference ports; 2 cabinets - 48 conference ports; 3 cabinets - 64 conference ports.
- Built-in Time of Day clock provides a minimum of 15 minutes hold up time when a +5 V power is removed. This will bridge short power outages and cover maintenance issues.
- Inclusion of Memory Daughterboard providing 24 Mb of flash ROM for program store and 8 Mb of flash ROM for the file system.
- RAM on SIMM can be upgraded should future applications require.
- DOS compatible file system.
- The main processor has a base configuration of 8Mb of DRAM for operating memory space
- Two PCMCIA slots accommodating two industry standard PCMCIA cards which can be used for a cost effective vehicle for software upgrading/updating or data storage devices. Slots are labelled as a: and b:. Slot a: is dedicated for the software delivery and patch delivery and slot b: is dedicated for External Data Card.
- New Software Delivery Process. Feature activation via keycodes which will be controlled via a security device specific to each site.
- New software installation/upgrade procedure.
- FLASH software daughterboard replacing Option 11 and 11E software cartridges remains with the system permanently.
- Flash daughterboard is expandable.
- Supports telenet, ftp, remote login for the SMP (System Management Products).
- New fiber interface for connecting up to two expansion cabinets to the main cabinet.
- Two new options of fiber-optic connectivity are provided - local 10m fixed length and remote up to 3 Km length.
- New fiber routing/cable management solutions.
- TTY improvements - 1 TTY on each expansion cabinet, 3 TTY ports on card 0 of main cabinet.

- Backward Compatible Daughterboard for copper connectivity upgrades from Option 11/11E.
- Database upgrade tool for data extraction from Option 11/11E software cartridges for customers who don't have remote backup capabilities.

Software

Option 11C requires X11 Release 22 and later versions of software.

Note: Release 22 and later versions of software cannot be used with existing Option 11 and Option 11E systems.

Hardware

- Commercially Based System Core Card NTDK20 with built-in ethernet & PCMCIA interface.
 - Flash ROM software daughterboard NTDK21.
 - Fiber expansion daughterboards - 2 versions: 10m (NTDK22) and up to 3 Km (NTDK24).
 - Expansion Cabinets fiber receiver packs - 2 versions: 10m (NTDK23) and up to 3 Km (NTDK25) provides interface to the main cabinet and includes local TTY port.
 - Fiber Optic Cables: 10m between cabinets (plastic) and up to 3 Km to remote cabinet (glass).
 - Backward compatible CPU daughterboard - NTDK26 provides upgrade path for existing Option 11 systems.
 - New expansion cabinet & backplane (same as the main cabinet).
 - Ethernet Connector Cable - NTDK27.
 - PCMCIA Card used for software delivery. Two versions 40 Mb for software delivery and 3 Mb for patch delivery.
 - Customer Database Upgrade tool - NTDK30 used for extracting the customer database from old Option 11 cartridges for upgrades where remote backup is not available.
-

- Security Device - NTDK57: Installation of software, feature set and ISM parameters is protected by a security device on the CPU board card and a site specific keycode scheme. The security device is installed as part of the new system installation.

Table 13: Hardware Components

Option 11E Hardware	Option 11C Hardware	Description
NTBK45	NTDK20	System Core Card
NTBK63	NTDK21	Flash Software Daughterboard (Blank)
NTBK54	NTDK22	10m Fiber Daughterboard
NTBK55	NTDK23	10m Fiber Receiver Pack
Included with NTBK55	A0632902	10m Fiber Cable
N/A	NTDK24	3 Km Fiber Daughterboard
N/A	NTDK25	3 Km Fiber Receiver Pack
N/A	NTDK26	Backward Compatible Daughterboard
N/A	NTDK27	Ethernet Cable
N/A	NTDK30	Customer Database Upgrade Tool
NTAK69/70 & NTBK79	NTDK50	Main/Expansion Cabinets
N/A	NTDK57	Security Device
N/A	P0816832	Fiber Routing Guide
N/A	A0633651	PCMCIA Card (Blank)
NTBK81	Not Required	Fiber Management Kit

Note: Glass cable for 3 Km fiber connectivity is provided by end user.

Note: Option 11E H/W codes listed above cannot be upgraded to 11C.

NTAK02BB Introduction

The vintage of the NTA02 has been advanced to incorporate new firmware that supports ISDN Signaling Link (ISL) Networking features developed in Release 21.44 and later, namely Trunk-Anti-Tromboning, Network call page and Network call park.

Customers planning to take advantage of these features are required to upgrade the NTA02 to the minimum vintage of NTA02BB - A0658092 QUAD SERIAL I/O (SPORT).

All new shipments that require NTA02 cards will automatically receive new vintage of NTA02.


Product Description

System Core Card (NTDK20)

The Option 11C CPU pack is a standard size, single slot Meridian 1 style circuit pack that resides in slot 0 of the main cabinet.

The Option 11C CPU card introduces a commercially based CPU (M68040 family) as the primary call processor. The CPU operates under the Wind Rivers Systems VxWorks real time operating system which is the same as the Meridian 1 Option 51C, 61C, and 81. It provides a real time improvement of more than 7 times (based upon configuration) over the Option 11E. The main features include:

- Main CPU: MC68LC040 running VxWorks.
 - Auxiliary CPU: MC68020.
 - More than 7 times Real Time increase over 11E.
 - Flash ROM program/file storage.
 - Built-in ethernet interface.
 - Built-in PCMCIA interfaces to support new software delivery mechanism.
 - Built-in Time of Day device (holds for up to 15 minutes).
 - Conference capability expanded (additional 1 loop allowing 16 more conferees).
 - Provides on board XMFC/MF functions.
 - 3 standard TTY ports.
 - Expandable SIMM DRAM operations memory.
-



The following hardware items can be mounted on the system core card:

- Software Flash Daughterboard.
- Fiber Expansion Daughterboards.
- Backward Compatible Daughterboard (in place of fiber expansion daughterboard).
- Security Device.
- Fiber Routing Guide.

Note: NTB45 (Option 11E System Core card) is not supported on Option 11C systems

PCMCIA Socket

The CPU has a faceplate accessible PCMCIA type III socket. This is a dual socket that can support either 2 PCMCIA type II cards such as FLASH cards, or a single PCMCIA type III card such as a Harddrive. The intent of the PCMCIA interface is to provide a software delivery interface to the system. All system software can be delivered on a PCMCIA card and transferred to the on-board FLASH software daughterboard. The PCMCIA interface provides a method of transferring software or upgrades to the system.

Security Device

Installation of software, feature set and ISM parameters is protected by a security device on the CPU card and a site specific keycode scheme. The security device is installed as part of the new system installation. The Security ID (8 digit number encoded on the security device) is a key component of the system tracking database. Each security device has a unique identification number and is not changeable on the device. As long as the security device stays with the system, the Security ID of the system remains the same.

There are three types of security devices:

Standard Security Device - site specific and requires keycode to activate software. The standard security device is required for every site.

Technology Security Device - used by Nortel Tech Lab.

Distributor Security Device - used by Distributor Tech Labs and doesn't require keycodes to activate software.

Tone Services

The Option 11C CPU pack extends the tone services and consolidates the remaining Meridian 1 tone services of MFC, MFE, KD3, & MF onto the CPU pack. While increasing the flexibility of the Option 11 product, it will also provide a cost reduction for those markets that require these signalling standards as they will no longer require a separate IPE pack for the function.

The Option 11C includes the capability of adding one of the following: XMFC or XMFE or KD3 or MF or DTR detection. This effectively imports the functionality of the (XMFC) or the (MF) packs. The new channels (4 MF/MFC or 8 XTD/DTR) will be able to support only one of the signalling protocols at a time as defined by software. This is not viewed as a limitation as the signalling protocols are primarily exclusive. That is, you would not require more than one of the protocols in a system at a time. If none of the new signalling protocols is required, an addition 8 channels of DTR can be supported.

Conference

The CPU supports 32 ports (conferees) on the base system. The base configuration can support up to 10 three party conferences or up to 4 six party conferences.


Conference capabilities has been expanded in increments of 16 ports per expansion box via the fiber expansion daughterboard. Therefore, the conference capability extends to 48 ports for two cabinets, and 64 ports for 3 cabinets.

Flash Software Daughterboard (NTDK21)

The delivery of software and firmware has been significantly improved for Option 11C. Software operation and storage is now provided via FLASH based technology residing on a daughterboard mounted on the CPU pack. The software cartridges will not be supported on the Option 11C systems.

Software will be delivered on the new systems and systems converting from Option 11/11E to Option 11C by a pre-programmed flash daughterboard. It contains a master copy of the software, pre-configured data, firmware, feature sets, and patches. The FLASH could be expanded should future applications require it. The highlights include:

- Used for software storage and operating space.
- Used for software delivery for new systems and 11/11E conversions to Option 11C.
- 24Mb for program store and 8 Mb for file system.
- Mounted on CPU pack in the main cabinet.
- Re-programmable.



Note: Upgrades to Option 11C systems do not require a new software daughterboard. The software upgrades are done via a PCMCIA card.

Note: Option 11/11E software cartridges are not supported on Option 11C.

Fiber Daughterboards (NTDK22 & NTDK24)

Expansion to 2nd and 3rd cabinet is done via CPU mounted fiber daughterboards. The system core card supports up to 2 fiber daughterboards. Each expansion cabinet requires one fiber daughterboard mounted on the CPU pack and one expansion cabinet fiber receiver pack installed in the expansion cabinet - slot 0. There are two versions of fiber daughterboards to support two different solutions namely:

- 10m fiber connectivity.
- 3 Km fiber connectivity.

The 10m fiber connectivity provides up to 10m of separation between the cabinets (main and expansion) via a plastic fiber cable. This allows flexibility in locating expansion cabinets on different floors. For 10m fiber, the NTDK22 Fiber Daughterboard is required.


The 3 Km fiber connectivity provides up to 3 Km of separation between the cabinets (main and expansion) via a glass fiber cable (customer supplied). This allows flexibility in locating expansion cabinets on a remote site or a campus environment. For 3 Km fiber - NTDK24 fiber Daughterboard is required.

Both fiber connectivities can co-exist i.e. a system can be configured with a 10m fiber connectivity to local expansion cabinet and 3 Km fiber connectivity to the remote expansion cabinet.

Note: Copper and fiber connectivity can not co-exist i.e. a system can not be configured with a copper connection to one expansion cabinet and fiber connection to the other expansion cabinet.

The main features of the fiber daughterboards are:

- Fiber connection to expansion cabinets.
 - Mounted on System Core Card (CPU).
 - Each expansion cabinet requires a fiber daughterboard on the main CPU maximum of two daughterboards are supported.
 - 2 versions (10m and upto 3 Km) - can co-exist on the same system.
 - Each daughterboard requires a corresponding fiber receiver pack to be installed in the expansion cabinet.
 - Built in conference.
-




Fiber Receiver Packs (NTDK23 & NTDK25)

The expansion cabinet fiber receiver pack is introduced to provide fiber transmitter and receiver interface to the main cabinet. There are two version of fiber receiver packs:

- 10m version - NTDK23.
- 3 Km version - NTDK25.

The main features include:

- Installed in slot 0 of each expansion cabinet.
- Provides fiber interface to main cabinet.
- Includes local TTY port.
- Fiber Routing Guide mechanism.
- 2 versions (10m and 3 km).



Fiber Routing Guides


The fiber routing guide is installed on the fiber receiver pack to manage the fiber cable.

Backward Compatible Daughterboard (NTDK26)

The Option 11C supports a CPU mounted daughterboard which provides a backward compatible solution for upgrades of existing Option 11/11E systems with copper expansion cable to the new Option 11C system maintaining copper connectivity. It is installed on the CPU board and has additional conference capabilities.

Note: This configuration

- Does not support ethernet interface (e.g. SMP ethernet connection).
- Does not support Option 11E fiber.
- Does not support Option 11C 10m and 3Km fiber expansion schemes.



Cabinets

The Option 11C introduces new expansion cabinets which are now same as main cabinets. The Option 11 /11E systems requiring conversions to Option 11C can maintain their old cabinets as long as no ethernet access and no fiber connectivity is required. The existing main cabinets can be maintained when converting to a 2 or 3 cabinet fiber Option 11C systems. The new cabinet code NTDK50 replaces the existing NTAK69, NTAK70, and NTBK79. There is no distinction between the main cabinet and expansion cabinets.

Note: System configuration and restrictions are the same as for Option 11E (i.e. Common Equipment (CPU board, Digital Trunks, etc.) can only be installed in the main cabinet.

The new codes are:

Table 14: New Cabinet Codes

New Cabinet Codes	Description	Region
NTDK50BA	Main/Expansion cabinet (FCC CLASS A)	North America, CALA, and AP
NTDK50DA	Main/Expansion Cabinet (CISPR CLASS B)	Europe
NTDK50FA	Main/Expansion Cabinet (Holland)	Holland
NTDK50GA	Main/Expansion Cabinet (CISPR CLASS A)	Europe, Asia Pacific

Fiber Optic Cables

There are two versions of fiber cable required for fiber connectivities:

- 10m plastic cable for 10m fiber connection between cabinets.
- Up to 3 Km glass cable for 3 Km fiber connection to remote cabinets.



Fiber Specification

Plastic Fiber Cable

This cable is not an industry standard. It is provided by Hewlett Packard to work with a proprietary plastic fiber interface. It must be 10 meters in length. This cable is supplied by Northern Telecom (A0632902).

Glass Fiber Cable Requirements

The cable is standard 62.5/125 um glass multimode duplex cable with ST style connectors. The cable is not provided by Nortel. Potential vendors are Hewlett Packard or AMP.

Table 15: Typical Requirements for Glass Fiber

Item	Min.	Typical	Max.
Cable Length			3 Km.
Cable Attenuation (@ 1300 nm)		1.5 dB/Km	2.0 dB/Km
Model Bandwidth (@ 1300nm)	200 Mhz*Km	500 Mhz*Km	
Chromatic Dispersion (@ 1300nm)		6 ps/nm*Km	
Typical 3 DB Bandwidth		180 Mhz *Km	

Note: The optical power budget for the glass fiber link is typically 8 dB. Fiber link is limited to a maximum length of 3 km, even though with many optical cables the optical power budget of 8 dB could support greater lengths. To guarantee reliable operation a bandwidth budget of 150% should be maintained. If the link is increased beyond 3 km length, the 150% margin is deteriorated possibly resulting in link malfunction under some conditions.

Note: Glass cable is customer supplied and can not be ordered from Nortel.

Ethernet Interface

The Option 11C CPU pack has a built-in 10 Mbps Ethernet port. This is consistent with the other members of the “C” based switches in the Meridian 1 family.

A 50 pin amphenol to 15 pin MAU adaptor cable is introduced to provide ethernet access.



Note: Ethernet connectivity is not available if the Backward Compatible Daughterboard (NTDK26) is in use.


PCMCIA Cards

The software for Option 11C systems can be delivered via a plug-in commercial PCMCIA card containing the new software and software installation program. It is primarily intended to deliver software upgrades to the existing Option 11C systems. It contains a master copy of the software, pre-configured data, firmware, feature sets, and patches which can be used by the distributors for installation/upgrades for a number of sites. Once the upgrade is completed successfully, the PCMCIA card can be removed from the Small System Controller card and reused at other sites. The main features include:

- Used for software, firmware, feature sets, and patches delivery.
- Can be used as an external memory storage device.
- Re-programmable.
- Single device can be used to upgrade multiple sites.
- 2 versions: 40 Mb for software delivery and 3 Mb for patch delivery only. See “Software Delivery Impact” section for details on PCMCIA model# supported on Option 11C.

Note 1: A PCMCIA card is not required during initial installation of the system, where only a pre-programmed software daughterboard is required.

Note 2: The 3 Mb PCMCIA patch delivery card is only required for patch delivery under circumstances where remote patch delivery via modem is not used.



Customer Database Upgrade Tool

Upgrade of an existing Option 11/11E system to Option 11C requires the retrieval and conversion of the data. Two methods used are:

Remote Backup and Restore Feature: The upgrade procedure requires the use of a PC equipped with Remote Backup and Restore tools. The PC is used to extract the data file from an existing Option 11 system and transfer it back to the Option 11C CPU. The installation program running on the Option 11C performs the conversion and database restore tasks.

Customer Database Upgrade Tool: At sites where remote backup and restore capabilities are not available, a Customer Database Upgrade Tool can be used to transfer the customer data contents from the existing 11/11E system cartridge to the Option 11C CPU. This is a tool which can be used at multiple sites and can be ordered from Nortel in addition to the Option 11C system hardware/software.

Tools Impact

Meridian Administration Tool

Meridian Administration Tools (MAT) Release 4.5 now supports X11 Release 22 as well as systems running X11 Release 14, 17, 19, 20 and 21. MAT Release 4.5 is designed for the Windows 3.1 operating system. MAT Release 4.5 provides the following Applications: Station Administration, Traffic Analysis, Call Accounting and Call Tracking.

Meridian Administration Tools (MAT) Release 5 is introduced with X11 Release 22 and requires the Windows 95 Operating System. MAT Release 5 provides the following applications: Station Administration, Traffic Analysis, Call Accounting, Call Tracking, Maintenance Windows, ESN Analysis and Routing Tool and Alarm Management.

MAT Release 5 also supports connectivity to Meridian 1 via Ethernet for System Options 11C, 51C through 81C running X11 Release 22. If MAT 5 is connected to a System type of 51C through 81C via Ethernet the following minimum vintage cards and cables are required:

- NT5D20BA (Release 01) - IOP/CMDU Card
- NT6D63BA (Release 01) - IOP Card (1 for each IOP/CMDU or IOP card)
- NT7D90DA (Release 01) - Ethernet Cable

Note: If MAT is connected via Ethernet a revised Parallel Upgrade procedure must be followed to ensure that the primary IP address remains active following a software upgrade. Please refer to the MAT Release 5 Common Services User Guide Release 5.0 (part number A0858266) for further details.

Meridian Configurator

Meridian Configurator has been modified to reflect Option 11C - Release 22.

Meridian Mail

There is no impact on Meridian Mail due to Option 11C introduction.

Customer Database Upgrade Tool

This is a tool which is required for sites requiring upgrade to an Option 11C that do not have Remote Backup capabilities. This new tool allows the data to be extracted from the Option 11/11E software cartridge for an upgrade to an Option 11C. Once the site upgrade has been completed, the tool can be used for other sites.

Software Delivery Impact

The following two software delivery media are used for Option 11C:

- **Pre-Programmed Flash Software Daughterboard: all new system installations and Option 11/11E conversions to Option 11C**
- **PCMCIA Card: Ongoing Option 11C software upgrades**

The software delivery for all new Option 11C and upgrades from existing Option 11/11E system to Option 11C is done via a pre-programmed FLASH software daughterboard.

The software delivery for Option 11C sites (new software releases) is done via a re-programmable 40Mb PCMCIA card. The same PCMCIA card can be used to upgrade multiple sites and can be re-programmed for future upgrades. Pre-programmed or blank cards can be ordered from Nortel. The programmed PCMCIA card contains a generic copy of all the software components for a particular release and all the feature set options and customer default data available for that specific country/region. Feature upgrade for existing Option 11C sites do not require PCMCIA cards because Packaging, ISM parameters etc. can be upgraded via obtaining new keycodes.

The PCMCIA cards can be duplicated/re-programmed at the distributor locations with an appropriate hardware setup as described below.

Note: Installation/upgrade of software, feature set, and ISM parameters requires site specific keycodes provided by Nortel.

PCMCIA Duplication Setup

To duplicate software from one PCMCIA card to other PCMCIA cards, the following hardware setup is required:

Hardware Set-up

- Personal Computer (386 or faster).
- Windows (recommended, but not essential).
- A PCMCIA drive & software for Flash ATA memory cards.

There are many PCMCIA drive/PC combinations on the market. The following lists setups that have been tried within Nortel, however these are not the only configurations that will work. When dealing with a local PC distributor, let them know that you are trying to program:

PCMCIA Flash devices supported on option 11C include:

Table 16: Supported 40Mb PCMCIA Cards

Vendor	Catalogue #
IBM	40G4315
Toshiba	TH6SS160402AAA

Table 17: Supported 3Mb PCMCIA Cards

Vendor	Catalogue #
Toshiba	TH6SS160031AAA

Example Configurations**Setup # 1**

- Pentium/75MHz
- PCNFS s/w
- Netscape
- Eiger ESA-2000. (2-slot PCMCIA ISA adapter)

Setup #2

- Go PC486 DX2/66
- Windows 3.11
- 3COM ethernet card (etherlink II 3c503)
- Netscape
- WFTP 4.00 s/w
- SCM Swapbox Classic X2 (works in windows)

Note: PCMCIA cards can be sent to Nortel for programming at nominal charge if distributors choose not to have the local software duplication setup.

Keycode Process Flow

Installation of software, feature set and ISM parameters is protected by a security device on the CPU board card and a site specific keycode scheme. The security device is installed as part of the new system installation.

Keycodes are required for each new installation as well as existing system upgrades. They are unique to each site for a particular combination of such items as software release, feature set, and ISM parameters.

The following steps are required to obtain keycodes:

- Distributor places order for new keycodes (site specific)

- The keycode is prepared by Nortel and sent via fax (if requested) and shipped overland. For emergencies the keycodes can be provided over the phone.

Upgrading an existing Option 11/11E to Option 11C

When upgrading from an Option 11 or Option 11E, the customer database must be extracted from the existing system. As the new Option 11C system will not utilize the existing cartridge, it will not be able to directly extract customer data from old cartridge. There are two methods of extracting the database:

- 1 By using the **Customer Configuration Backup and Restore (CCBR)** feature and a Personal Computer (PC). The PC is used to extract the data from an existing Option 11/11E system and transfer it back to the Option 11C CPU. The installation program running on the Option 11C CPU will perform the conversion and database restore tasks.
- 2 Alternately, at sites where a PC is not available for remote backup and restore, a **Customer Database Upgrade Tool (NTDK30)** can be used to transfer the customer data contents from the cartridge to the Option 11C CPU.

The following table highlights the hardware required for upgrading an existing Option 11/11E systems to an Option 11C system under various configurations. For a detailed list of items, use standard tools.

Table 18: Upgrade Option 11/11E to Option 11C

Initial Configuration	Upgrade to	Physical Changes
1-cabinet Option 11 or 1-cabinet Option 11E	1-cabinet Option 11C	System Core Card Flash ROM Daughterboard Ethernet cable/adaptor
	2-cabinet Option 11C	System Core Card Flash ROM Daughterboard Ethernet cable/adaptor Expansion Cabinet Fiber Expansion Daughterboard Fiber Receiver Pack Fiber Optic Cable
	3-cabinet Option 11C	System Core Card Flash ROM Daughterboard Ethernet cable/adaptor Expansion Cabinet (2) Fiber Expansion Daughterboard (2) Fiber Receiver Pack (2) Fiber Optic Cable (2)

Table 18: Upgrade Option 11/11E to Option 11C

Initial Configuration	Upgrade to	Physical Changes
2-cabinet Option 11 or 2-cabinet Option 11E with copper cable connection	2-cabinet Option 11C with copper cable con- nection Note: No Ethernet Connectivity in this configuration	System Core Card Flash ROM Daughterboard Backward Compatible Daughterboard
	2-cabinet Option 11C	System Core Card Flash ROM Daughterboard Ethernet cable/adaptor Expansion Cabinet Fiber Expansion Daughterboard Fiber Receiver Pack Fiber Optic Cable
	3-cabinet Option 11C	System Core Card Flash ROM Daughterboard Ethernet cable/adaptor Expansion Cabinet (2) Fiber Expansion Daughterboard (2) Fiber Receiver Pack (2) Fiber Optic Cable (2)
2-cabinet Option 11E with fiber connection	2-cabinet Option 11C	System Core Card Flash ROM Daughterboard Ethernet cable/adaptor Expansion Cabinet Fiber Expansion Daughterboard Fiber Receiver Pack Fiber Optic Cable

Table 18: Upgrade Option 11/11E to Option 11C

Initial Configuration	Upgrade to	Physical Changes
	3-cabinet Option 11C	System Core Card Flash ROM Daughterboard Ethernet cable/adaptor Expansion Cabinet (2) Fiber Expansion Daughterboard (2) Fiber Receiver Pack (2) Fiber Optic Cable (2)
3-cabinet Option 11E	3-cabinet Option 11C	System Core Card Flash ROM Daughterboard Ethernet cable/adaptor Expansion Cabinet (2) Fiber Expansion Daughterboard (2) Fiber Receiver Pack (2) Fiber Optic Cable (2)

Upgrading Option 11C Software

The software delivery for upgrades to Option 11C systems is done via a re-programmable 40Mb PCMCIA card. The same PCMCIA card can be used to upgrade multiple sites and can be re-programmed on future upgrades.

Pre-programmed or blank cards can be ordered from Nortel. The programmed PCMCIA card contains a generic copy of all the software components for a particular release and issue (e.g. 22.16) as well as all the feature set options and customer default data available for that specific country/region.

The blank cards can be programmed at the distributor location via downloading the software from the internet, see section Electronic Software Delivery for internet registration.

Keycodes are required for activating the new software. They are unique to each site for a particular combination of such items as software release, feature set, and ISM parameters. New keycodes must be ordered for each site to activate the new software release.

Auxiliary Products Compatibility

X11 Release 22 supports the following releases of Auxiliary products.

Table 19: Auxiliary Product Compatibility

Auxiliary Processor	Release	Comments
Meridian Link	2-4 4B,5.x	Application Module and IPE Module
Visit Video (Mac)	1.0	
Visit Video (Windows)	1.1	
Visit Voice(Mac)	1.0	
Visit Voice(Windows)	1.1	
Visit Messenger	3.0	
Visit Personal Assistant	2.0	
Visit Fast Call (Windows)	1.1	
CPlus (Base)	3.11	
CPlus 2000	3.13 or later	
CPlus LANKey	1.0	
CPlus Performer	1.0 and later	
Meridian Mail	8.x-11.x	
Meridian Mail Card option	8.x-11.x	

Table 19: Auxiliary Product Compatibility

Auxiliary Processor	Release	Comments
Meridian Customer Controlled Routing	2.x, 3.x 3B	Application Module Application Module & IPE Module
ACD MAX	4.x	
Meridian MAX	4.x-7.x	Application Module & IPE Module
IPE Max	4 or later	
Interactive Voice Response	1.x - 2.x	US, Canada, and Asia Pacific
	2.x	Europe
Meridian Interactive Voice Response	1.x - 3.x	
Open Interactive Voice Response	2.x+	
M911	1.x - 2.x	
Meridian Administration Tools (Windows 3.1) (Windows 95)	4.5	Station Admin., Traffic Analysis, Call Accounting, Call Tracking In Addition alarm management, Maint. windows, and ESN
	5	
Network Administration Center	1.x, 2.x	

Meridian 1

Option 11C

General Release Bulletin

© 1998 Northern Telecom

All rights reserved

Information is subject to change without notice. Northern Telecom reserves the right to make changes in design or components as progress in engineering and manufacturing may warrant. This equipment has been tested and found to comply with the limits for a Class A digital device pursuant to Part 15 of the FCC rules.

Meridian 1 is a trademark of Northern Telecom.

Document release: Standard Issue 4.0

Date: March 1998

Printed in Canada