

# FEPS Registry Patch for BCM 3.0

## Problem:

BCM 3.0/3.0.1 systems are not ready, out of the box, to interoperate with BCM 3.6 systems. This can cause dropped calls, and event 201s on the BCM 3.0/3.0.1 system.

## Solution:

This patch is applied to a BCM 3.0/3.0.1 system to make it ready to interoperate with BCM 3.6 systems. A section is added into the registry setting certain parameters necessary for the BCM3.6 system to be recognized and treated properly.

## BCM Release and Affected Profiles:

BCM 3.0/3.0.1