

# **i2050 Software Phone (build 314)**

**Patch Description:** The purpose of this patch is to transfer the i2050 Software Phone client to the BCM 3.0 system.

## **SR/CRs fixed (versus BCM 3.0 GA):**

- Q00630199: i2050 Directory: crash when reading Outlook XP (2002) contact email addresses
- Q00630190: i2050 Directory: crash if decline access while importing Outlook XP contacts
- Q00621685: i2050 couldn't import phone details from vcf file
- Q00635222: i2050 phone feature keys do not illuminate when active
- Q00420401: ACD Agent logged in on i2050 has no Lgged In Information
- Q00112436: i2050 call center phone icons are incorrect
- Q00319367: i2002/50 set when a CFWD (F4) is programmed on a key Indicator does not work

## **Software Components Changed:**

i2050 Software Phone client

## **BCM Release and Affected Profiles:**

- BCM 3.0 RC 2.2 version 4
- BCM 3.0 RC 2.2U version 4