

FEPS Registry Patch for BCM 3.5

Problem:

BCM 3.5 systems are not ready, out of the box, to interoperate with BCM 3.6 systems. This can cause dropped calls.

Solution:

This patch is applied to a BCM 3.5 system to make it ready to interoperate with BCM 3.6 systems. A section is added into the registry setting certain parameters necessary for the BCM3.6 system to be recognized and treated properly.

BCM Release and Affected Profiles:

BCM 3.5