

BCM 3.5 T.38 Forward Capability for BCM 3.5

CRs Resolved:

- Q00807584 : T.38 FAX does not function to Succession 3.0 with additional fix for forward compatibility

BCM Release and Affected Profiles:

- BCM 3.5