BCM 3.7 Alarm Monitor Update

Patch: BCM 3.7 Alarm Monitor for JITC Certification

Date: January 4th, 2006

Applicable Platform: BCM 3.7

Recommendation: Non-critical. Recognizes and reports two new CoreTel alarms which deal with the Digital Trunk Interface MBM

Component & Version: Alarm Monitor 36.1.1.46

Dependencies: Core Telephony WI 07.08 for BCM 3.7

Size: 1.5 MB

System Impact: Time to apply is 20 minutes, two reboots are required

The following issues are addressed:

- Addition of alarms 336 and 372 for DTI MBM

Status:

- Generally Available -