

ipView Soft Board 1.4.004 client for BCM 3.0

Patch Description:

The purpose of this patch is to transfer the ipView Soft Board Client to the BCM 3.0 system.

CR's Resolved: (Since BCM 3.0 GA - ipView 1.4.002)

ipView Soft Board 1.4.004 - released to Nortel April 12th 2003

- Q00636852-02: ipView could crash on some Windows XP and Windows 2000 machines (exception generated in Microsoft MFC42.DLL) if it was set to echo to more than 16 other wallboards or softboards. This has been corrected.

Release Notes:

- [Release note](#)

Software Components Changed:

- ipView Soft Board client application. This application does not run on the BCM but on Client PC's.

BCM Release and Affected Profiles:

- BCM 3.0 RC2.2
- BCM 3.0 RC2.2 U