

Media Transport MT_DS30 Patch for BCM 3.5

Problem Description

This patch will prevent a very intermittent Bug Check when under extremely heavy VoIP traffic load.

Solution Description

A glare condition in the driver was identified.

List of CRs Resolved:

Q00779184

Software Components Changed:

Media Transport DS30 driver (a component of the Voice MSC Driver package).

BCM Release and Affected Profiles:

- BCM 3.5