BCM 3.6 Phase II Set FW v. D4B Update

CRs Resolved:

- Q00944566 Fix on DHCP/VLAN
- Q01024821 Speakerphone/Handsfree is unusable on IP Set

Other Changes:

Miscellaneous new selftest from wistron to include flash lock sector test Miscellaneous RUDP fix possible packet drop when packet come in phone out of order

Status:

• Generally Available