

# BCM 3.6 Unified Manager Patch

**Applicable Platform:** BCM 3.6

**Recommendation:** Critical

**Component and Version:** BCM3.6 GA

**Dependencies:** None

## The following issues are addressed:

- Q00907581 - BCM 3.5 does not show all the remote gateways programmed.  
(Only 25 of them)
- Q00881489 - "Incremental Payload Size" control is missing in unified manager
- Q00944339 - LAN1 and 2 goes down after restarting the router with patch
- Q00944340 - LED's keep on Blinking after applying patch  
BCM\_350.011\_UM.39.1002-LAN Down
- Q00956906 - ISDN Link doesn't establish after applying the patch  
BCM\_350.011\_UM.39.1002
- Q00935053 - BT/JLP/BCM crashes when multiple connections on same Callback user
- Q00934446 - RAS Callback not working correctly
- Q01103195 - G729 Payload displayed as 0ms after CP2 applied

## Status:

- Generally Available