## **BCM 3.6 Alarm Monitor Update**

This patch updates the Voice Software Alarm Monitor so that Core Telephony logevent 135 is reported in the NT Event Application Log.

## Status:

• Generally Available -