

BCM050.054-CONFIGFS--- VERSION: 1.0 --- RELEASE:1.4

Applicable Platform: BCM 50 R1, Release 2.04G and 2.04J.

Recommendation: Non-critical

Component & Version: CONFIGFS 2.27.0

Dependencies: None

Size: Less than 1 mb

System Impact: Takes less than 1 minute to install. There will be no interruption to system operation. Please note and follow the installation instructions below.

Issues Resolved:

- o Q01147853 After a Level 1 reset, it is not possible to dial into the BCM50 soft modem. The modem answers but it does not complete the handshake and the connection attempt always fails. The issue will only occur after a Level 1 reset because the recovery modem configuration files are incorrect. This patch replaces the current modem configuration files if required and ensures that any subsequent Level 1 reset will maintain the correct versions of the modem configuration files.

Limitations: None