UNISTIM Terminal Proxy Server for BCM 3.5

"IP Sets Not Responding"

Problem:

UTPS did not handle the reception of short Reliable UDP packets correctly and it caused all IP sets to lose connection with the BCM

Solution:

New logic was added to properly discard packets that do not meet the minimum size requirement.

CRs Resolved:

- Q00876828
- Q00871752
- Q00834995

BCM Release and Affected Profiles:

• BCM 3.5